9/22/21, 9:56 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21007381/EVCN2

22/09/2021 Date:

REFERENCE

China Taiping Insurance (Singapore) Handling Insurer:

Policy No:

DMPCSNW00135392004

Claimant Vehicle

Pte. Ltd.

Insured Vehicle

No:

SMW6789T

No:

SKV8874X

TP

Date of Loss:

02/07/2021

Nature of Claim:

Claim SNM21D203736/C02 No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMW6789T

Make & Model:

BMW X5, 3.0 (A) 18/03/2020 (Man. Year: 2019) Engine No:

15695841B58B30C

Reg. Date: Colour:

Grey

Chassis No: Odometer:

WBACR620509B42746

Engine Capacity:

2998 сс

19419 km

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: Nο

Yes

CONDITION OF TYRES

Front Tyre Size:

275/45R20

Rear Tyre Size:

275/45R20

Front Left Side:

Bridgestone 4 mm

Rear Left Side:

Bridgestone 4 mm

Front Right Side:

Bridgestone 4 mm

Rear Right Side:

Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,430.70	603.80	826.90	57.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,092.00	2,004.00	1,088.00	35.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,522.70	2,607.80	1,914.90	42.34
+ GST 7.00/7.00% (S\$)	316.59	182.55	134.04	42.34
Nett Amount (S\$)	4,839.29	2,790.35	2,048.94	42.34

INSPECTION

Date of Assignment:

06/07/2021

Performance Motors Limited (Alexandra)

Date Inspected: 07/09/2021 Inspected At: 303 Alexandra Road, Sime Darby Performance

Centre

Singapore 159941

Estimated Period of Repair:

3.0 days

Adjuster: **CHEN TSUE YEE** Manager:

VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

REPAIR DETAILS

Reference

9/22/21, 9:56 AM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Sep 2021)

Parts: M1-SUV BMW X5 3.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMW6789T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR UNDERRIDE PROTECTION TRIM (X L)	Cut	552.30 FS	*552.30 FS
2	4		*DECOUPLING RING	Not Necessary	20.60 FS	*- FS
3	2		*ULTRASONIC SENSOR ARCTIC GREY WC27	Not Necessary	766.30 FS	*- FS
4	1		*SUNDRIES	Necessary	80.00 FS	*40.00 FS
5	10		*BLIND RIVET	Necessary	11.50 FS	*11.50 FS
F=Fra	anchise	part. S=SpcN	Nett.	-		
				Total Parts (S\$)	1,430.70	603.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPLACE REAR BUMPER UNDERRIDE TRIM,ATTACHMENT ITEMS CAUSE BY ACCIDENT.REMOVE AND INSTALL REAR BUMPER FOR REPAIR	New	1,700.00	850.00
2	TO SPRAY PAINT REAR BUMPER	New	1,038.00	986.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	0.00
	Gross Labour Cost (S\$)		3,092.00	2,004.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >