

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007382/DVCN2**Date:** 23/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00074172100

Claimant Vehicle No : SKE9690S **Insured Vehicle No :** SJE3620X

Date of Loss: 01/07/2021 Nature of Claim: TP Claim No: SNM21D203702/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKE9690S**

Make & Model: CITROEN C4, 1.6 (A) Engine No: 10XT190234009

Reg. Date: 01/08/2016 (Man. Year: 2016) Chassis No: VF7NCHNYTGY502587

Colour: Red Odometer: 85460 km

Engine Capacity: 1199 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	42,108.50	5,958.49	36,150.01	85.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,500.00	980.00	5,520.00	84.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	48,608.50	6,938.49	41,670.01	85.73
Approved Total (Overridden) (\$\$)		5,550.00		
(\$\$)	48,608.50	5,550.00	43,058.50	88.58
+ GST 7.00/7.00% (\$\$)	3,402.60	388.50	3,014.10	88.58
Nett Amount (\$\$)	52,011.10	5,938.50	46,072.60	88.58

INSPECTION

Date of Assignment: 30/11/2021

Date Inspected: 06/07/2021 Inspected At: C.s.ong Auto Pte Ltd (HQ)
10, ANG MO KIO IND PARK 2A #02-16 AMK
AUTO POINT SINGAPORE 568047
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2021)
Parts:	144	CITROEN C4 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE9690S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	2,980.00 FL	*- FL
2	1		*BONNET INSULATOR	Not Necessary	285.00 FL	*- FL
3	1		*BONNET LOCK	Not Necessary	395.00 FL	*- FL
4	1		*BONNET STRIKER LOCK	Not Necessary	105.00 FL	*- FL
5	1		*BONNET SEAL	Not Necessary	95.00 FL	*- FL
6	2		*BONNET HINGE LH/RH	Not Necessary	298.00 FL	*- FL
7	1		*FRONT GRILLE	Not Necessary	492.00 FL	*- FL
8	1		*FRONT GRILLE CHROME	Not Necessary	520.00 FL	*- FL
9	2		*HEAD LAMP LH/RH	Broken	7,100.00 FL	*3,536.00 FL
10	2		*HEAD LAMP LOWER BRACKET LH/RH	Not Necessary	390.00 FL	*- FL
11	2		*HEAD LAMP ECU LH/RH	Not Necessary	3,640.00 FL	*- FL
12	1		*HEAD LAMP WIRE HARNESS	Serviceable	2,420.00 FL	*- FL
13	1		*FRONT BUMPER	Dented	2,680.00 FL	*989.00 FL
14	2		*FRONT BUMPER SIDE RETAINER LH/RH	Serviceable	296.00 FL	*- FL
15	1		*FRONT BUMPER GRILLE	Bent/Deformed	385.00 FL	*385.00 FL
16	2		*FRONT BUMPER FOG LAMP LH/RH	Not Necessary	900.00 FL	*- FL
17	2		*FRONT BUMPER FOG LAMP GARNISH LH/RH	Not Necessary	270.00 FL	*- FL
18	2		*FRONT BUMPER FOG LAMP CHROME LH/RH	Not Necessary	390.00 FL	*- FL
19	2		*FRONT BUMPER FOG LAMP HOLDER LH/RH	Not Necessary	240.00 FL	*- FL
20	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	Not Necessary	1,925.00 FL	*- FL
21	1		*FRONT BUMPER UNDER COVER	Not Necessary	437.00 FL	*- FL
22	1		*FRONT REINFORCEMENT BAR	Bent	1,450.00 FL	*683.10 FL
23	1		*FRONT BUMPER SPONGE	Not fitted	398.00 FL	*- FL
24	1		*FRONT SUPPORT PANEL	Not Necessary	1,680.00 FL	*- FL
25	1		*FRONT BRACE PANEL	Not Necessary	195.00 FL	*- FL
26	1		*INTER-COOLER ASSY	Not Necessary	2,980.00 FL	*- FL
27	1		*A/C CONDENSOR ASSY	Not Necessary	2,104.00 FL	*- FL
28	1		*A/C CONDENSOR SUCTION HOSE	Not Necessary	1,005.00 FL	*- FL
29	1		*A/C CONDENSOR DISCHARGE HOSE	Not Necessary	789.00 FL	*- FL
30	1		*A/C CONDENSOR LOWER GARNISH	Not Necessary	342.00 FL	*- FL
31	1		*RADIATOR ASSY	Not Necessary	2,003.00 FL	*- FL
32	1		*RADIATOR TOP HOSE	Not Necessary	95.00 FL	*- FL
33	1		*RADIATOR BOTTOM HOSE	Not Necessary	104.00 FL	*- FL
34	1		*RADIATOR FAN MOTOR	Not Necessary	617.00 FL	*- FL
35	1		*RADIATOR FAN BLADE	Not Necessary	395.00 FL	*- FL
36	1		*RADIATOR FAN COWLING	Not Necessary	872.00 FL	*- FL
37	2		*FRONT FENDER LH/RH	Not Necessary	2,900.00 FL	*- FL
38	2		*FRONT FENDER INNER SHIELD LH/RH	Not Necessary	390.00 FL	*- FL
39	2		*FRONT FENDER QUARTER GLASS MOULDING LH/RH	Not Necessary	620.00 FL	*- FL
40	1		*FRONT BUMPER CENTER BRACKET	Deformed/Cracked	396.00 FL	*396.00 FL
41	1		*FRONT CENTER AIR GUIDE	Broken	587.00 FL	*587.00 FL
42	1		*BONNET INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*FRONT GRILLE CLIPS	Serviceable	50.00 FS	*- FS
45	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
46	1		*FRONT BUMPER GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

12/23/21, 10:18 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*FRONT FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
49	1		*FRONT FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
50	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
51	1		*COOLANT	Not Necessary	100.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					46,725.00	6,616.10
- List Item Discount on L Items 10.00/10.00% (S\$)					4,616.50	657.61
Total Parts (S\$)					42,108.50	5,958.49
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	300.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
5	TO RNR FRONT INTER-COOLER ASSY TO FACILITATE REPAIRS	New	200.00	0.00
6	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	0.00
7	TO RNR RADIATOR ASSY & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00
8	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
9	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (\$\$)			6,500.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >