

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21007385/APS3Q2
Date: 05/10/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SKE900X

Date of Loss: 04/07/2021

Policy No:

Insured Vehicle No :

Nature of Claim:

SMN1346T

TP

Claim No: 8855539111SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKE900X**

Make & Model: AUDI A3, 1.4 TFSI (A)

Reg. Date: 30/04/2015 (Man. Year: 2015)

Colour: Black

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: CZC248570

Chassis No: WAUZZZ8V4FA143776

Odometer: 74923 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Handbrake (Serviceable):

Yes

Steering (Serviceable):

Engine Modification:

Yes

No

Footbrake (Serviceable):

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Front Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Tyre Size:

Rear Left Side:

Rear Right Side:

225/40 R18

Goodyear 6 mm

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,471.00	1,656.00	1,815.00	52.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,422.00	1,522.00	900.00	37.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,893.00	3,178.00	2,715.00	46.07
+ GST 7.00/7.00% (S\$)	412.51	222.46	190.05	46.07

Nett Amount (S\$)	6,305.51	3,400.46	2,905.05	46.07
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,557.91		

INSPECTION

Date of Assignment: 08/07/2021

Date Inspected: 08/07/2021

Estimated Period of Repair: 3.0 days

Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,070.00 FS	*1,656.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS
3	2		*REAR BUMPER LOCKING MECHANISM -LH/RH	Not Necessary	28.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	237.00 FS	*- FS
5	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	603.00 FS	*- FS
6	2		*REAR BUMPER BRACKET LH/RH	Not Necessary	26.00 FS	*- FS
7	2		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
8	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
9	1		*EXHAUST TRIM (NPA)	Not Necessary	0.00 FS	*- FS
10	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$)	3,471.00
						1,656.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR PARKING AID .CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER REORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,422.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >