

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 814X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / MTG DISTORTED	896.00	681.10
1	REAR BUMPER BRACKET	SERVICEABLE	72.30	-
2	REAR BUMPER SIDE RETAINER @\$47.00	N/S DISTORTED	94.00	47.00
1	REAR BUMPER SPONGE	SERVICEABLE	94.30	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	346.23	-
1	REAR TAIL LAMP L/H	SERVICEABLE	397.90	-
1	REVERSE SENSOR SET (4 SENSORS)	SERVICEABLE	720.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	463.20	-
1	REAR END TOP PANEL GARNISH	SERVICEABLE	97.60	-
1	BOOT LID	TO REPAIR SEE LABOUR	888.00	-
	LESS 20% DISCOUNT		-813.91	-145.62
			3,255.62	582.48
1	TAIL GATE H LOGO	NECESSARY	38.70	38.70
1	CIVIC EMBLEM	NECESSARY	43.80	43.80
1	1.6 I-VTEC EMBLEM	NECESSARY	38.90	38.90
	LESS 20% DISCOUNT		-	-24.28
			121.40	97.12
	SPECIAL NETT ITEMS			
6	REAR BUMPER CLIP @\$6.50 (SN)	NECESSARY	39.00	39.00
1	REAR NUMBER PLATE (SN)	DENTED	25.00	25.00
			64.00	64.00
	<u>LABOUR</u>			
	SPRAY PAINT DAMAGED AREA AFFECTED.		600.00	400.00
	TO KNOCK & STRAIGHTEN REAR CHASSIS FRAME & CHANGE ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT, REAR END PANEL AND BOOT LID.		900.00	300.00

Report Ref No. CS/SMO21007401/Ktf3n2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

1,150.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	CHANGE TAIL LAMP AND CHECK WIRING.		85.00	10.00
			1,585.00	710.00
	GRAND TOTAL		5,026.02	1,453.60

Report Ref No. CS/SMO21007401/Ktf3n2

**RECOMMENDED COST OF LUMP SUM REPAIRS** 

(TO ITS PRE-ACCIDENT CONDITION)

KONG SENG CHEONG

Licensed Appraiser