

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007405/TGA3**Date:** 18/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100471675
Claimant Vehicle No :	FBQ5784A	Insured Vehicle No :	SLD5743T
Date of Loss:	26/06/2021	Nature of Claim:	TP
		Claim No:	3900330002SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ5784A		
Make & Model:	YAMAHA AEROX GDR155A, 155cc CVT ABS	Engine No:	G3J1E0441294
Reg. Date:	05/11/2019 (Man. Year: 2019)	Chassis No:	MH3SG4620KJ069739
Colour:	Yellow/Black	Odometer:	0 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/80 R14	Rear Tyre Size:	110/80 R14
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,577.50	3,157.10	4,420.40	58.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	970.00	290.00	680.00	70.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,547.50	3,447.10	5,100.40	59.67
Approved Total (Overridden) (\$\$)		2,600.00		
Nett Amount (\$\$)	8,547.50	2,600.00	5,947.50	69.58
+ Loss of Use (7.0 x S\$20.00/day) (\$\$)		140.00		
Nett Liability (\$\$)		2,740.00		

INSPECTION

Date of Assignment:	07/07/2021	Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ) 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit Singapore 417883
Date Inspected:	07/07/2021 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Bent	980.00 FL	*300.00 FL
2	1		*FORK UNDER BRACKET	Not Necessary	190.00 FL	*- FL
3	1		*FRONT SPORT RIM	Not Necessary	550.00 FL	*- FL
4	1		*FRONT BRAKE DISC	Not Necessary	180.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Bent	52.00 FL	*25.00 FL
6	1		*HEADLAMP	Cut	550.00 FL	*380.00 FL
7	1		*SET SIDE MIRROR	Cut	120.00 FL	*120.00 FL
8	1		*HANDLE -BAR	Bent	135.00 FL	*78.00 FL
9	1		*SET HANDLE -BAR BALANCER	Cut	98.00 FL	*50.00 FL
10	1		*SET HAND GRIP	Cut	78.00 FL	*78.00 FL
11	1		*BRAKE LEVER	Cut	104.00 FL	*28.00 FL
12	1		*SET FRONT SIGNALS	Cracked	160.00 FL	*90.00 FL
13	1		*FRONT SIDE INNER COVER	Cracked	250.00 FL	*150.00 FL
14	1		*FRONT CENTER LOWER COVER	Cracked	185.00 FL	*120.00 FL
15	1		*FOOTSTEP PANEL	Cracked	285.00 FL	*150.00 FL
16	1		*FOOTSTEP PANEL LOWER COVER	Distorted	340.00 FL	*180.00 FL
17	1		*BELT COVER	Cracked	175.00 FL	*175.00 FL
18	1		*AIR FILTER COVER	Cut	125.00 FL	*125.00 FL
19	1		*EXHAUST ASSY	Not Necessary	680.00 FL	*- FL
20	1		*EXHAUST PROTECTOR	Not Necessary	48.00 FL	*- FL
21	1		*MAIN STAND	Bent	180.00 FL	*80.00 FL
22	1		*SET FAIRING COVER	Cracked	1,450.00 FL	*650.00 FL
23	1		*SET NUMBER PLATE	Not Necessary	28.00 FS	*- FS
24	2		*FORK OILS	Necessary	30.00 FS	*30.00 FS
25	2		*FORK OIL SEALS	Necessary	56.00 FS	*56.00 FS
26	1		*STEERING CONE	Necessary	120.00 FS	*90.00 FS
27	1		*SET FRONT SLIDER	Bent	180.00 FS	*120.00 FS
28	1		*REAR BOX	Cut	520.00 FS	*300.00 FS
29	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS
30	1		*REAR TYRE	Not Necessary	120.00 FS	*- FS
31	1		*SET STICKER	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,269.00	3,435.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	691.50	277.90
Total Parts (\$\$)	7,577.50	3,157.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	60.00	60.00
2	TO PROVIDE WIRING AND RESET HEADLAMP FOCUSING	New	80.00	30.00
3	TO REPAIR BODY FRAME	New	380.00	0.00
4	TO PROVIDE LABOUR	New	450.00	200.00
Gross Labour Cost (\$\$)			970.00	290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >