

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/GRB21006817/VTF3E2-1**Date:** 05/08/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SMA8493Z **Insured Vehicle No :** SLX6561P
 Date of Loss: 16/06/2021 Nature of Claim: TP Claim No: MFL2021D0002559

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA8493Z**
 Make & Model: TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A) Engine No: 3ZRB438552
 Reg. Date: 18/12/2014 (Man. Year: 2014) Chassis No: ZSU600023159
 Colour: Brown Odometer: 136466 km
 Engine Capacity: 1986 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,870.86	5,025.07	6,845.79	57.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	1,430.00	1,680.00	54.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,980.86	6,455.07	8,525.79	56.91
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	14,980.86	5,200.00	9,780.86	65.29

INSPECTION

Date of Assignment: 07/07/2021
 Date Inspected: 18/06/2021 Inspected At: A S Auto Service (HQ)
 Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Aug 2021)		
Parts:	N/A	TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMA8493Z)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented / Warped	1,803.50 FL	*1,803.50 FL
2	1		*SET TAILGATE GLASS MOULDING	Necessary	297.54 FL	*297.54 FL
3	1		*TAILGATE GLASS	Serviceable	1,218.20 FL	*- FL
4	1		*TAILGATE OUTER GARNISH	Serviceable	591.65 FL	*- FL
5	1		*TAILGATE EMBLEM HARRIER	Necessary	96.65 FL	*96.65 FL
6	2		*TAILGATE LAMP	Cracked / Water Seeped In	822.70 FL	*822.70 FL
7	1		*TAILGATE INNER LOCK	Bent / Jammed	681.59 FL	*450.00 FL
8	1		*TAILGATE INNER BOARD	Not Necessary	481.93 FL	*- FL
9	1		*TAILGATE WEATHERSTRIP	Serviceable	341.66 FL	*- FL
10	2		*TAILGATE AUTO DAMPER	Serviceable	2,706.20 FL	*- FL
11	2		*TAILGATE STOPPER	Necessary	25.20 FL	*25.20 FL
12	1		*COMPUTER MULTIPLEX NETWORK DOOR	Malfunction	489.97 FL	*489.97 FL
13	2		*TAILLAMP	Serviceable	983.50 FL	*- FL
14	1		*REAR BUMPER	Dented / Deformed	1,389.30 FL	*1,389.30 FL
15	1		*REAR BUMPER DIFFUSER	Grazed / Deformed	491.90 FL	*491.90 FL
16	2		*REVERSE SENSOR	Damaged / Broken	963.80 FL	*250.00 FL
17	2		*REAR BUMPER REFLECTOR	Serviceable	252.40 FL	*- FL
18	1		*REAR BUMPER SPONGE	Broken	241.33 FL	*200.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	220.50 FL	*150.00 FL
20	1		*REAR END PANEL	Repair	1,006.40 FL	*- FL
21	1		*REAR END PANEL TRIM	Serviceable	361.89 FL	*- FL
22	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*50.00 FS
23	1		*SET TAILGATE GLASS FOAM TAPE	Necessary	65.00 FS	*40.00 FS
24	1		*SET TAILGATE OUTER GARNISH CLIP	Necessary	80.00 FS	*40.00 FS
25	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,737.81	6,641.76
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,866.95	1,616.69
Total Parts (\$\$)	11,870.86	5,025.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIX TAILGATE GLASS	New	180.00	120.00
2	TO CHECKING REAR ELECTRICAL WIRING SYSTEM	New	50.00	20.00
3	TO REMOVE, REFIX REAR INTERIOR TRIM TO ASSIST REPAIR	New	100.00	50.00
4	TO REMOVE, REFIX REVERSE CAMERA & SENSOR	New	80.00	50.00
5	TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	New	180.00	60.00
6	TO RESPRAY UNDERCOATING	New	120.00	30.00
7	TO RESPRAY PAINTING & ETC	New	1,200.00	500.00
8	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS	New	1,200.00	600.00
Gross Labour Cost (\$\$)			3,110.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >