

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007408/TQC�2**Date:** 01/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00107052002

Claimant Vehicle No : SGP6281Z **Insured Vehicle No :** SJH8989J

Date of Loss: 26/06/2021 Nature of Claim: TP Claim No: SNM21D203677/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGP6281Z**

Make & Model: MAZDA 3, 1.6 SP Lux (A) Engine No: Z6513607

Reg. Date: 21/12/2006 (Man. Year: 2006) Chassis No: JM6BK106270328190

Colour: Red Odometer: 269078 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,126.08	1,694.40	5,431.68	76.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	430.00	2,620.00	85.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,176.08	2,124.40	8,051.68	79.12
Approved Total (Overridden) (\$\$)		1,700.00		
Nett Amount (\$\$)	10,176.08	1,700.00	8,476.08	83.29

INSPECTION

Date of Assignment: 07/07/2021

Date Inspected: 12/07/2021 Inspected At: 8 KAKI BUKIT AVENUE 4
PREMIER @ KB #01-51/52
REPAIRER: 1ST AUTO PRO PTE LTD

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2022)
Parts:	143	MAZDA 3 1.6 SP Lux (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGP6281Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,090.80 FL	*- FL
2	1		*BONNET STOPPER LH	Not Necessary	111.20 FL	*- FL
3	1		*BONNET STOPPER RH	Not Necessary	111.20 FL	*- FL
4	1		*BONNET RUBBER FRONT	Not Necessary	127.50 FL	*- FL
5	1		*BONNET RUBBER REAR	Not Necessary	122.40 FL	*- FL
6	1		*BONNET HINGE LH	Not Necessary	145.20 FL	*- FL
7	1		*BONNET HINGE RH	Not Necessary	145.20 FL	*- FL
8	1		*BONNET LOCK ASSY	Not Necessary	288.00 FL	*- FL
9	1		*FRONT BUMPER	Deformed	976.20 FL	*976.20 FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	690.60 FL	*- FL
11	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	128.40 FL	*- FL
12	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	128.40 FL	*128.40 FL
13	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	580.00 FL	*- FL
14	1		*FRONT BUMPER FOG LAMP WITH COVER LH	Not Necessary	371.10 FL	*- FL
15	1		*FRONT BUMPER FOG LAMP WITH COVER RH	Not Necessary	371.10 FL	*- FL
16	1		*FRONT GRILLE ASSEMBLY	Not Necessary	392.20 FL	*- FL
17	1		*FRONT BRACE PANEL	Not Necessary	139.70 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Not Necessary	566.00 FL	*- FL
19	1		*HEADLAMP LH	Not Necessary	975.90 FL	*- FL
20	1		*HEADLAMP RH	Cracked	975.90 FL	*975.90 FL
21	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
22	1		*FRONT NUMBER PLATE WITH CASING	Not Necessary	100.00 FS	*- FS
23	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	220.60 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,857.60	2,110.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,731.52	416.10
Total Parts (\$\$)	7,126.08	1,694.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIT AND TRANSFER FRONT BUMPER COMPONENT	New	150.00	0.00
2	TO REMOVE AND REFIT ELECTRICAL WIRING,REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONONG-FRONT	New	150.00	30.00
3	TO REMOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR-FRONT	New	150.00	0.00
4	TO APPLY UNDERCOATING ON REPLACED AND REPAIRED PANELS FOR RUST PROTECTION	New	100.00	0.00
5	TO PROVIDE SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS	New	1,000.00	200.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO ORIGINAL POSITION USING POWER TOOLS	New	1,500.00	200.00
Gross Labour Cost (\$\$)			3,050.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >