

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21007411/RVCQ2**Date:** 21/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00034042100

**Claimant Vehicle No :** SNA989B **Insured Vehicle No :** SBJ333M

Date of Loss: 03/07/2021 Nature of Claim: TP Claim No: SNM21D203751/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNA989B**

Make & Model: LAMBORGHINI HURACAN, 5.2 LP610-4 (M) Engine No: CSJ005978

Reg. Date: 03/05/2017 (Man. Year: 2016) Chassis No: ZHWEC2ZF9GLA04857

Colour: Black Odometer: 21469 km

Engine Capacity: 5204 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 245/35Z R19 Rear Tyre Size: 245/35Z R19

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	62,982.19	55,059.59	7,922.60	12.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	26,110.00	15,410.00	10,700.00	40.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>89,092.19</b>	<b>70,469.59</b>	<b>18,622.60</b>	<b>20.90</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	6,236.45	4,932.87	1,303.58	20.90
<b>Nett Amount (\$\$)</b>	<b>95,328.64</b>	<b>75,402.46</b>	<b>19,926.18</b>	<b>20.90</b>

**INSPECTION**

Date of Assignment: 07/07/2021

Date Inspected: 07/07/2021 Inspected At: Eurosports Auto Pte Ltd (HQ)  
24 Leng Kee Road #01-03  
Singapore 159096

Estimated Period of Repair: 8.0 days

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Apr 2022)
<b>Parts:</b>	M1-COUPE	LAMBORGHINI HURACAN 5.2 LP610-4 (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNA989B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT DOOR	Bent	36,180.00 F	*32,562.00 F
2	1		*DOOR SEAL	Necessary	549.00 F	*494.10 F
3	1		*DOOR CATCH RUBBER	Not Necessary	8.68 F	*- F
4	1		*DOOR CATCH	Not Necessary	63.44 F	*- F
5	20		*DOOR COVER CAP	Not Necessary	24.00 F	*- F
6	20		*DOOR BUNGS	Not Necessary	20.80 F	*- F
7	5		*DOOR REINFORCEMENT S SCREW	Necessary	20.20 F	*18.25 F
8	1		*DOOR REINFORCEMENT S RUBBER	Necessary	21.16 F	*19.04 F
9	1		*DOOR REINFORCEMENT	Not Necessary	100.20 F	*- F
10	5		*DOOR CATCH SCREWS	Not Necessary	28.40 F	*- F
11	10		*DOOR CATCH SCREWS	Not Necessary	23.60 F	*- F
12	1		*DOOR HINGE (UPPER LEFT)	Not Necessary	61.16 F	*- F
13	1		*DOOR HINGE (LOWER LEFT)	Not Necessary	103.64 F	*- F
14	1		*HINGE REINFORCEMENT (UPPER LEFT)	Not Necessary	153.88 F	*- F
15	1		*HINGE REINFORCEMENT (LOWER LEFT)	Not Necessary	153.88 F	*- F
16	5		*DOOR HINGE SCREWS	Necessary	19.40 F	*17.45 F
17	10		*DOOR HINGE CAP	Not Necessary	18.80 F	*- F
18	1		*LEFT SIDE MEMBER	Cracked	3,255.00 F	*2,929.50 F
19	1		*LEFT SILL TRIM STRIP	Necessary	355.60 F	*320.04 F
20	1		*SIDE MEMBER HOLDER (ARM)	Broken	61.04 F	*47.59 F
21	1		*RADIATOR GRILLE	Not Necessary	800.80 F	*- F
22	1		*SIDE MEMBER INNER BRACKET	Not Necessary	154.80 F	*- F
23	1		*SIDE MEMBER ARM (FRONT)	Broken	30.00 F	*27.00 F
24	1		*SIDE MEMBER ARM (REAR)	Not Necessary	60.00 F	*- F
25	1		*SEAL	Not Necessary	16.64 F	*- F
26	2		*COMPENSATING PIECE (SCREW)	Necessary	30.00 F	*25.66 F
27	10		*EXPANDING NUT	Necessary	24.40 F	*22.10 F
28	10		*SPEED NUT	Necessary	20.40 F	*18.50 F
29	1		*DOOR CATCH	Necessary	63.44 F	*57.11 F
30	1		*DOOR CATCH SCREW	Not Necessary	5.68 F	*- F
31	10		*DOOR CATCH SCREW	Necessary	23.60 F	*21.20 F
32	1		*REAR LEFT FENDER	Bent	20,505.00 F	*18,454.50 F
33	5		*12 SOCKET HEAD BOLT	Necessary	25.55 F	*25.55 F

F=Franchise part.

**Total Parts (\$)** **62,982.19** **55,059.59**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR	New	8,000.00	4,800.00
2	SPRAY PAINTING	New	6,400.00	4,000.00
3	BODY WRAP	New	2,800.00	2,500.00
4	REAR FENDER REPLACEMENT AND SPRAY PAINTING	New	6,400.00	4,000.00
5	REAR BUMPER REMOVAL	New	1,600.00	0.00
6	RESPRAY SIDE MIRROR HOUSING	New	800.00	0.00
7	TOWING	New	110.00	110.00
<b>Gross Labour Cost (\$\$)</b>			<b>26,110.00</b>	<b>15,410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >