

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 6066S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (SN)	DENTED	2,070.00	2,070.00
1	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	193.00	-
2	REAR BUMPER LOCKING MECHANISM LH RH (SN)	NOT NECESSARY	28.00	-
1	REAR WHEEL HOUSING LINER ADAPTER RH (SN)	NOT NECESSARY	38.00	-
1	REAR BUMPER SPOILER (SN)	CRUSHED	237.00	237.00
1	REAR LIGHT REFLECTOR RH (SN)	BROKEN	30.00	29.50
1	LED TAIL LIGHT RH OUTER (SN)	NOT NECESSARY	877.00	-
1	LED TAIL LIGHT RH INNER (SN)	NOT NECESSARY	877.00	-
1	REAR BUMPER REINFORCEMENT BEAM (SN)	NOT NECESSARY	603.00	-
1	REAR BUMPER BRACKET LH (SN)	NOT NECESSARY	27.00	-
1	REAR BUMPER BRACKET RH (SN)	NOT NECESSARY	29.00	-
1	REAR BUMPER GUIDE SECTION RH (SN)	BROKEN	67.00	66.20
4	REAR SENSOR SEAL RING (SN)	NOT NECESSARY	14.00	-
2	REAR SENSOR INNER / OUTER (SN) (NPA)	NOT NECESSARY	-	-
1	REAR VENT TRIM RH (SN)	NOT NECESSARY	33.00	-
1	SUNDRIES (SN)	NECESSARY	300.00	7.20
			5,423.00	2,409.90
	<u>LABOUR</u>			
	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.		280.00	280.00
	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS TAIL LAMP PANEL AND REAR END PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		2,100.00	700.00
	TO RESPRAY REAR BUMPER, RHS TAILLAMP PANEL AND REAR END PANEL.		2,800.00	700.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			5,372.00	1,872.00
	GRAND TOTAL		10,795.00	4,281.90

Report Ref No. CS/SMR21007413/Euf3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			4,281.90
-----------------------------	--	--	----------

Report Ref No. CS/SMR21007413/Euf3e2



Automotive Assessor



ANG BRYAN TANI

Automotive Assessor / Investigator