

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007414/ATCE2**Date:** 23/08/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00076112004

Claimant Vehicle No : GBC6143S **Insured Vehicle No :** YN8855C

Date of Loss: 05/07/2021 Nature of Claim: TP Claim No: SNM21D203743/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC6143S**

Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2261055

Reg. Date: 29/04/2013 (Man. Year: 2013) Chassis No: JTFAT35YX0K202190

Colour: Silver Odometer: 0 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C

Front Left Side: Bridgestone 6 mm Rear Left Side: Maxxis 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,090.90	17,331.65	25,759.25	59.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,980.00	7,020.00	4,960.00	41.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	55,070.90	24,351.65	30,719.25	55.78
Approved Total (Overridden) (\$\$)		18,000.00		
Nett Amount (\$\$)	55,070.90	18,000.00	37,070.90	67.31

INSPECTION

Date of Assignment: 16/08/2021

Date Inspected: 07/07/2021 Inspected At: Hiap Hong Motor Repair
2 Kaki Bukit Avenue 2, #02-13
Singapore 417921

Estimated Period of Repair: 18.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Aug 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC6143S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
2	1		*FRONT BUMPER	Bent	589.40 F	*589.40 FL
3	2		*FRONT BUMPER BRACKET	Bent	450.20 F	*450.20 FL
4	1		*FRONT GRILLE	Missing	587.20 F	*587.20 FL
5	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
6	1		*FRONT GRILLE LOGO	Missing	86.90 F	*86.90 FL
7	2		*HEADLAMP	Cracked	1,362.40 F	*1,362.40 FL
8	1		*FRONT PANEL	Distorted	1,019.30 F	*1,019.30 FL
9	1		*FRONT CORNER PANEL	O/S Distorted	516.40 F	*258.20 FL
10	1		*FRONT PANEL TOP MOULDING	Cracked	266.40 F	*266.40 FL
11	1		*FRONT PANEL TOP MOULDING (SIDE)	O/S Missing	245.40 F	*122.70 FL
12	1		*WIPER PANEL	Distorted	418.90 F	*418.90 FL
13	1		*WIPER PANEL SIDE COVER	O/S Cracked	415.40 F	*212.70 FL
14	1		*FRONT WINDSCREEN	Shattered	1,288.30 F	*1,288.30 FL
15	1		*FRONT WINDSCREEN MOULDING	Necessary	285.10 F	*285.10 FL
16	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
17	2		*WIPER ARM	Bent	230.00 F	*230.00 FL
18	2		*WIPER BLADE	Cut	70.00 F	*70.00 FL
19	1		*WIPER NOZZLE	O/S Cracked	137.00 F	*68.50 FL
20	1		*WIPER MOTOR	Damaged	591.70 F	*591.70 FL
21	1		*WIPER LINKAGE	Bent	387.70 F	*387.70 FL
22	1		*ERP BRACKET	Necessary	26.00 FS	*26.00 FS
23	1		*DASHBOARD	Deformed	985.20 F	*985.20 FL
24	1		*DASHBOARD REINFORCEMENT	Bent	635.00 F	*635.00 FL
25	1		*CENTRE CONSOLE COVER	Cracked	349.20 F	*349.20 FL
26	1		*GLOVE BOX	Cracked	298.40 F	*298.40 FL
27	1		*SPEEDOMETER	Not Necessary	1,035.40 F	*- FL
28	1		*STEERING COLUMN COVER	Not Necessary	210.40 F	*- FL
29	1		*AIR CON BLOWER	Cracked	1,135.10 F	*1,135.10 FL
30	1		*AIR CON EVAPORATOR	Cracked	1,089.40 F	*1,089.40 FL
31	1		*BRAKE MASTER PUMP	Not Necessary	367.10 F	*- FL
32	1		*BRAKE BOOSTER PUMP	Not Necessary	806.20 F	*- FL
33	1		*BRAKE BOOSTER PUMP BRACKET	Bent	225.50 F	*225.50 FL
34	1		*AIR CON CONDENSER	Not Necessary	955.30 F	*- FL
35	1		*RADIATOR	Not Necessary	1,637.60 F	*- FL
36	2		*ENGINE MOUNTING	Not Necessary	483.40 F	*- FL
37	1		*FRONT RH DOOR	Distorted	1,310.80 F	*1,310.80 FL
38	1		*FRONT RH DOOR LOCK	Jammed	346.10 F	*346.10 FL
39	1		*FRONT RH DOOR WEATHERSTRIPE	Cut	238.60 F	*238.60 FL
40	1		*FRONT RH DOOR INNER TRIM BOARD	Cracked	581.10 F	*581.10 FL
41	1		*FRONT RH DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
42	2		*FRONT RH DOOR HINGE	Bent	297.20 F	*297.20 FL
43	1		*FRONT RH DOOR CHECK	Bent	75.90 F	*75.90 FL
44	1		*FRONT RH DOOR GLASS	Shattered	408.10 F	*408.10 FL
45	1		*FRONT RH DOOR GLASS OUTER MOULDING	Deformed	115.10 F	*115.10 FL
46	1		*FRONT RH DOOR GLASS REGULATOR GEAR	Damaged	295.70 F	*295.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT RH DOOR GLASS REGULATOR MOTOR	Not Necessary	509.00 F	*- FL
48	1		*FRONT RH DOOR PILLAR	Repair	764.20 F	*- FL
49	1		*FRONT RH DOOR WING MIRROR	Not Necessary	313.80 F	*- FL
50	1		*FRONT RH DOOR COMPANY ADDRESS STICKER	Necessary	30.00 FS	*30.00 FS
51	1		*FRONT RH STEP GARNISH	Not Necessary	241.10 F	*- FL
52	2		*CABIN REAR PILLAR	Repair	1,078.80 F	*- FL
53	1		*CABIN REAR WINDSCREEN	Shattered	202.10 F	*202.10 FL
54	1		*CABIN REAR WINDSCREEN MOULDING	Necessary	85.00 F	*85.00 FL
55	1		*CABIN REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
56	1		*CABIN LOCK LEVER	Jammed	398.50 F	*398.50 FL
57	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
58	1		*REAR NUMBER PLATE BRACKET	Bent	155.10 F	*155.10 FL
59	1		*REAR NUMBER PLATE LAMP	Not Necessary	69.50 F	*- FL
60	1		*REAR STEP PANEL	Bent	250.00 FS	*180.00 FS
61	2		*TAILLAMP	Cracked	503.60 F	*503.60 FL
62	2		*TAILLAMP PANEL	Bent	238.60 F	*238.60 FL
63	2		*STOPPER	Cut	50.00 FS	*50.00 FS
64	2		*STOPPER BRACKET	Bent	337.20 F	*337.20 FL
65	1		*TAILGATE	Distorted	1,116.70 F	*1,116.70 FL
66	4		*TAILGATE HINGE	Bent	202.00 F	*202.00 FL
67	2		*TAILGATE SIDE LOCK	Bent	321.00 F	*321.00 FL
68	2		*TAILGATE SIDE LOCK LATCH	Bent	90.00 F	*90.00 FL
69	1		*TAILGATE LOWER PANEL	Dented	485.90 F	*485.90 FL
70	1		*TOYOTA STICKER	Necessary	176.50 F	*176.50 FL
71	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
72	1		*13 PAX STICKER	Necessary	10.00 FS	*10.00 FS
73	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
74	1		*REAR EXHAUST PIPE	Not Necessary	585.20 F	*- FL
75	1		*REAR EXHAUST MOUNTING	Not Necessary	45.10 F	*- FL
76	1		*REAR CANOPY	Bent	1,000.00 FS	*450.00 FS
77	2		*SIDE GATE	Repair	3,730.40 F	*- FL
78	2		*SIDE GATE ADVERTISEMENT STICKER	Necessary	560.00 FS	*400.00 FS
79	1		*SPARE TYRE LOCK	Not Necessary	366.10 F	*- FL
80	1		*REAR DECK CARRIER	Repair	5,800.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	43,090.90	22,580.20
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	5,248.55
Total Parts (S\$)	43,090.90	17,331.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING (FRONT)	New	2,800.00	1,500.00
2	SPRAY PAINTING (FRONT)	New	2,500.00	1,600.00
3	WIRING (FRONT)	New	100.00	30.00
4	TO SPRAY TUFF COAT (FRONT)	New	280.00	150.00
5	TO REMOVE UPHOLSTERY	New	250.00	120.00
6	TO REMOVE DASHBOARD	New	350.00	220.00
7	TO REPLACE FRONT WINDSCREEN	New	180.00	120.00
8	TO REMOVE AIRCON SYSTEM AND TO TOP UP AIR CON GAS	New	350.00	200.00
9	TO TRANSFER DOOR FITTINGS	New	150.00	80.00
10	TO REPLACE CABIN REAR WINDSCREEN	New	120.00	80.00
11	PANEL BEATING (REAR)	New	1,200.00	800.00
12	SPRAY PAINTING (REAR)	New	1,800.00	1,000.00
13	WIRING (REAR)	New	100.00	30.00
14	TO SPRAY TUFF COAT (REAR)	New	150.00	80.00
15	TO REMOVE REVERSE SENSOR	New	100.00	50.00
16	TO REMOVE REAR DECK CARRIER	New	350.00	280.00
17	TO REPAIR AND STRAIGHTEN REAR CHASSIS MEMBER	New	800.00	500.00
18	TO REMOVE REAR CANOPY	New	250.00	180.00
19	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (\$\$)			11,980.00	7,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >