



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: ANG YVONNE			Ref: CS/ASM21007419/Ktce2 Date: 01/11/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1171Y	Veh. Inspected	GBE 5243H	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M03450	Excess (\$)	0.00	
Assign From	YU DOMINIC YISHAN	Assign Date	07/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (A)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTFHT02P500188011	Colour	SILVER	
Odometer	194255 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	FALKEN	9 mm	
L/H Front Tyre	195 R15X8	FALKEN	9 mm	
R/H Rear Tyre	195 R15X8	FALKEN	9 mm	
L/H Rear Tyre	195 R15X8	FALKEN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2021	Inspection Date	30/09/2021	
Survey held at	CHOON HOCK MOTOR TRADING CO BLK 176 SIN MING DRIVE #05-03 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	