



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                 |  |  |
|--|--|-----------------|--|--|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811<br>ATTN: ANG YVONNE   |  |                 | Ref: CS/ASM21007419/Ktce2<br>Date: 01/11/2021<br>Code: ASM |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                 |  |  |
| Insured Veh.   | SHC 1171Y  | Veh. Inspected  | GBE 5243H  |  |
| Policy No.   | VFX/P2419138   | Coverage (\$)   | 0.00   |  |
| Claim No.  | S1M03450   | Excess (\$)     | 0.00   |  |
| Assign From  | YU DOMINIC YISHAN  | Assign Date     | 07/07/2021   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                 |  |  |
| Make & Model   | TOYOTA HIACE (M)   | c.c             | 2982   |  |
| Engine No.   | HIDDEN   | Year of Reg.    | 2016   |  |
| Chassis No.  | JTFHT02P500188011  | Colour          | SILVER   |  |
| Odometer   | 194255 KM  | Steering        | IN ORDER   |  |
| Brakes   | IN ORDER   | Modification    | NIL  |  |
| General  | GOOD   |                 |  |  |
| <b>3. Conditions of Tyres</b>  |  |                 |  |  |
|  | Size   | Make            | Balance  |  |
| R/H Front Tyre   | 195 R15X8  | FALKEN          | 9 mm   |  |
| L/H Front Tyre   | 195 R15X8  | FALKEN          | 9 mm   |  |
| R/H Rear Tyre  | 195 R15X8  | FALKEN          | 9 mm   |  |
| L/H Rear Tyre  | 195 R15X8  | FALKEN          | 9 mm   |  |
| <b>4. Description of Damages</b>   |  |                 |  |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.<br>DAMAGES SEE DETAILS.  |  |                 |  |  |
| <b>5. General Information</b>  |  |                 |  |  |
| Accident Date  | 28/02/2021   | Inspection Date | 30/09/2021   |  |
| Survey held at   | CHOON HOCK MOTOR TRADING CO<br>BLK 176 SIN MING DRIVE<br>#05-03<br>SIN MING AUTOCARE<br>SINGAPORE 575721 |                 |  |  |
| <b>5a. Remarks</b>   |  |                 |  |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |  |  |
| <b>5b. Estimate Days of Repair</b>   |  |                 |  |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  |                 | <b>3 Working Days</b>                                      |  |