



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 4910L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR LEFT UPPER ALUMINIUM SIDE PANEL (SN)	BENT / GRAZED	1,200.00	700.00
1	REAR LEFT OUTER ALUMINIUM SIDE PANEL (SN)	BENT / GRAZED	1,500.00	900.00
1	SET REAR LEFT DOOR STICKER (SN)	NECESSARY	500.00	250.00
			3,200.00	1,850.00
LABOUR				
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR LEFT AFFECTED AREA AND REPLACE REAR LEFT DAMAGED PARTS.		800.00	600.00
	TO PUTTY AND SPRAY PAINTING REAR LEFT PORTION.		800.00	600.00
	TO APPLY ANTI RUST PROOFING TO REAR LEFT AFFECTED AREA.		120.00	80.00
			1,720.00	1,280.00
GRAND TOTAL			4,920.00	3,130.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CS3/LPC21002493/T1vf3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.