

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21007423/T1QF3N2**Date:** 29/10/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MW007029
Claimant Vehicle No :	SHB6275D	Insured Vehicle No :	SBA3848Y
Date of Loss:	05/07/2021	Nature of Claim:	TP
		Claim No:	M2103153

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB6275D	Engine No:	2ZR2F59003
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU303089656
Reg. Date:	05/12/2019 (Man. Year: 2019)	Odometer:	195678 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,825.00	1,502.67	322.33	17.66
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,380.00	940.00	440.00	31.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,216.00	2,453.67	762.33	23.70
+ GST 7.00/7.00% (S\$)	225.12	171.76	53.36	23.70
Nett Amount (S\$)	3,441.12	2,625.43	815.69	23.70

INSPECTION

Date of Assignment:	07/07/2021		
Date Inspected:	07/07/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Oct 2021)
Parts: 144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB6275D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER REAR	Cracked	458.60 FL	-	*458.60 FL
2	1		*REAR BUMPER LOWER COVER	Deformed	552.60 FL	-	*552.60 FL
3	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	318.80 FL	-	*318.80 FL
4	1		*REAR BUMPER TOW COVER	Not Necessary	82.70 FL	-	*- FL
5	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	225.40 FL	-	*- FL
6	1		*REAR BUMPER REFLECTOR LH	Not Necessary	55.00 FL	-	*- FL
7	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
8	1		*REAR TRUNK LOGO PRIUS	Necessary	52.90 FL	-	*52.90 FL
9	1		*REAR TRUNK LOGO HYBRID	Necessary	52.40 FL	-	*52.40 FL
10	1		*REAR TRUNK COMFORT & TEL NUMBER	Necessary	60.00 FS	-	*60.00 FS
11	1		*REAR TRUNK COMFORT APP.	Necessary	40.00 FS	-	*40.00 FS
12	1		*REAR BUMPER ADVERTISEMENT	Not Necessary	50.00 FS	-	*- FS
13	1		*REAR BUMPER REVERSE SENSOR	Not Working	135.70 FS	-	*135.70 FS
Supplementary #1							
14	1		*COVER REAR FLOOR	Deformed	232.00 FL	-	*232.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,338.10	1,925.00
- List Item Discount on L Items 25.00/25.00% (S\$)	513.10	422.33
Total Parts (S\$)	1,825.00	1,502.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	600.00	350.00
2	SPRAY PAINTING	New	600.00	500.00
3	CHECK WIRING & LIGHTING	New	60.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
5	TOWING FEE	New	60.00	60.00
			Gross Labour Cost (\$\$)	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >