

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21007427/R1PS3Q2  
**Date:** 19/11/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0004773
<b>Claimant Vehicle No :</b>	SLM8286D	<b>Insured Vehicle No :</b>	CB8025E
Date of Loss:	04/07/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002897

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLM8286D</b>		
Make & Model:	AUDI A5, 2.0 TFSI QUATTRO (A)	Engine No:	CDN143242
Reg. Date:	28/09/2010 (Man. Year: 2010)	Chassis No:	WAUZZZ8TXBA013865
Colour:	Black	Odometer:	179238 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,844.88	2,072.34	2,772.54	57.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	1,050.00	640.00	37.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,534.88</b>	<b>3,122.34</b>	<b>3,412.54</b>	<b>52.22</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,500.00</b>		

<b>Nett Amount (S\$)</b>	<b>6,534.88</b>	<b>2,500.00</b>	<b>4,034.88</b>	<b>61.74</b>
<b>+ Car Rental (4.0 x S\$160.00/day) (S\$)</b>		640.00		
<b>Nett Liability (S\$)</b>		<b>3,140.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,100.00</b>		

INSPECTION

Date of Assignment: 07/07/2021

Date Inspected: 08/07/2021

Estimated Period of Repair: 3.0 days

Inspected At: Jas Auto Services (HQ)  
6D Mandai Estate, #03-02 M-Space  
Singapore 729938

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 Aug 2021)	
<b>Parts:</b>	N/A	AUDI A5 2.0 TFSI QUATTRO (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLM8286D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	900.80 FL	*900.80 FL
2	1		*FRONT BUMPER FOG LAMP COVER RH	Serviceable	160.50 FL	*- FL
3	1		*FRONT BUMPER SENSORS	Serviceable	350.00 FL	*- FL
4	1		*FRONT BUMPER HEADLAMP WIPER RH	Serviceable	235.40 FL	*- FL
5	1		*FRONT BUMPER HEADLAMP WIPER COVER RH	Cracked	128.40 FL	*128.40 FL
6	1		*FRONT BUMPER RETAINER RH	Serviceable	96.30 FL	*- FL
7	1		*FRONT BUMPER TOW COVER	Serviceable	32.10 FL	*- FL
8	1		*FRONT BUMPER LOWER LIP	Cracked	323.40 FL	*323.40 FL
9	1		*HEADLAMP RH	Scratched	950.00 FL	*950.00 FL
10	1		*FRONT FENDER RH	Repair	680.50 FL	*- FL
11	1		*BONNET	Serviceable	1,105.30 FL	*- FL
12	1		*INTERCOOLER PIPING	Serviceable	420.50 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,383.20</b>	<b>2,302.60</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	538.32	230.26
<b>Total Parts (\$)</b>	<b>4,844.88</b>	<b>2,072.34</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS ,ALL RELEVANT ATTACHMENTS FITTINGS TO COMMENCE REPAIRS ,REPLACE THE DAMAGED PARTS ,REINSTALL & REALIGN ALL NECESSARY PARTS	New	800.00	500.00
2	TO PUTTY & RESPRAY PAINT ON THE RELEVANT REPAIRED AREAS	New	800.00	550.00
3	TO RUST PROOF AFFECTED AREAS WHERE NECESSARY	New	90.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,690.00</b>	<b>1,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >