



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|----------------------------|-----------------|---|--|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | | Ref: CS3/CTI20014587/Kvce2-1 Date: 28/07/2021 Code: CTI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION) | | | | |
| Insured Veh. | XE 4761A | Veh. Inspected | SLB 5878Z | |
| Policy No. | DMCVSNW00017042001 | Coverage (\$) | 0.00 | |
| Claim No. | SNM20D205086/C02/TANKL | Excess (\$) | 0.00 | |
| Assign From | IRENE TAY | Assign Date | 08/07/2021 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | VOLVO XC60 (A) | c.c | 1969 | |
| Engine No. | HIDDEN | Year of Reg. | 2014 | |
| Chassis No. | YV1DZ40CDE2568815 | Colour | METALLIC LIGHT BROWN | |
| Odometer | 130258 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 235/60 R18 | MICHELIN | 6 mm | |
| L/H Front Tyre | 235/60 R18 | MICHELIN | 6 mm | |
| R/H Rear Tyre | 235/60 R18 | MICHELIN | 4 mm | |
| L/H Rear Tyre | 235/60 R18 | MICHELIN | 4 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 23/12/2020 | Inspection Date | 09/07/2021 | |
| Survey held at | 14 AMK ST 63 BLK B | | | |
| Repairer | ASSURE AUTO ASSIST PTE LTD | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 5 Working Days | |