

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007434/EVCN2**Date:** 24/08/2021REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00054892001
Claimant Vehicle No :	SKK9289L	Insured Vehicle No :	GBD1866S
Date of Loss:	05/07/2021	Nature of Claim:	TP
		Claim No:	SNM21D203774/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK9289L	Engine No:	13425482B48B20B
Make & Model:	BMW 530I, 2.0 LED NAV (A)	Chassis No:	WBAJR32010BJ16401
Reg. Date:	31/12/2018 (Man. Year: 2018)	Odometer:	52264 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R19	Rear Tyre Size:	245/40R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,919.40	6,433.40	486.00	7.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,733.00	3,893.00	1,840.00	32.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,652.40	10,326.40	2,326.00	18.38
+ GST 7.00/7.00% (S\$)	885.67	722.85	162.82	18.38
Nett Amount (S\$)	13,538.07	11,049.25	2,488.82	18.38

INSPECTION

Date of Assignment:	08/07/2021	Performance Motors Limited (Alexandra)
Date Inspected:	26/07/2021 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	5.0 days	Singapore 159941

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2021)
Parts:	143	BMW 530I 2.0 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK9289L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	14		*C CLIP FOR PLASTIC NUT	Not Necessary	15.40 FS	*- FS
2	1		*RH FOG LAMP SUPPORT	Not Necessary	65.35 FS	*- FS
3	1		*RH BUMPER GUIDE	Not Necessary	16.95 FS	*- FS
4	1		*FRT BUMPER PANEL PRIMED (PMA)	Dented	1,384.80 FS	*1,384.80 FS
5	10		*EXPANDING RIVET D=8MM	Necessary	11.00 FS	*11.00 FS
6	1		*RH HEADLIGHT LED AHL HIGH (ICON LIG)	Broken	4,887.60 FS	*4,887.60 FS
7	1		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	5.15 FS	*- FS
8	1		*PDC SENSOR SOPHISTOGRAU II W	Not Necessary	383.15 FS	*- FS
9	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
					Total Parts (S\$)	6,919.40
						6,433.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	2,975.00	1,275.00
2	TO RESPRAY FRONT BUMPER AND FRONT RIGHT FENDER	New	1,923.00	1,826.00
3	TO REPLACE RIGHT HEADLIGHT	New	481.00	456.00
4	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
5	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	168.00
Gross Labour Cost (\$\$)			5,733.00	3,893.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >