

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG21005241/DTF3E2-1
Date: 23/08/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001313056
Claimant Vehicle No :	SKM3093M	Insured Vehicle No :	SKA2706Z
Date of Loss:	26/04/2021	Nature of Claim:	TP
		Claim No:	256550

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM3093M	Engine No:	LEB5631066
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71092027
Reg. Date:	26/06/2019 (Man. Year: 2018)	Odometer:	121308 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Habilead 5 mm	Rear Left Side:	Habilead 5 mm
Front Right Side:	Habilead 5 mm	Rear Right Side:	Habilead 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,779.52	844.24	10,935.28	92.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,450.00	440.00	5,010.00	91.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,229.52	1,284.24	15,945.28	92.55
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	17,229.52	1,000.00	16,229.52	94.20
+ GST 7.00/7.00% (S\$)	1,206.07	70.00	1,136.07	94.20
Nett Amount (S\$)	18,435.59	1,070.00	17,365.59	94.20

INSPECTION

Date of Assignment:	28/04/2021	JWG International Pte Ltd (HQ)
Date Inspected:	28/04/2021 Inspected At:	Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
		AutoPoint
		Singapore 568047
Estimated Period of Repair:	2.0 days	

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2021)
Parts: M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM3093M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Not Affected	1,760.40 FL	*- FL
2	1		*TAILGATE EMBLEM (LOGO)	Not Necessary	62.50 FL	*- FL
3	1		*TAILGATE EMBLEM (FREED)	Not Necessary	87.78 FL	*- FL
4	1		*TAILGATE EMBLEM (HYBRID)	Not Necessary	91.56 FL	*- FL
5	1		*TAILGATE REFLECTOR LH	Not Necessary	465.45 FL	*- FL
6	1		*TAILGATE WEATHERSTRIP	Not Necessary	388.98 FL	*- FL
7	1		*TAILLAMP LH	Not Affected	879.00 FL	*- FL
8	1		*TAILLAMP LOWER BRACKET LH	Not Affected	195.00 FL	*- FL
9	1		*RR BUMPER (W/COL)	Dented / Deformed	1,065.99 FL	*925.80 FL
10	2		*RR BUMPER RETAINER R/L	Serviceable	169.80 FL	*- FL
11	1		*RR BUMPER REFLECTOR LH	Serviceable	92.80 FL	*- FL
12	1		*RR BUMPER BRACKET LH	Dented / Cracked	92.00 FL	*92.00 FL
13	1		*RR END PANEL	Repair	953.70 FL	*- FL
14	1		*RR END PANEL GARNISH	Not Affected	235.44 FL	*- FL
15	1		*RR LOCK ANTENNA	Not Affected	474.84 FL	*- FL
16	1		*RR KEYLESS ENTRY WARNING BUZZER	Not Affected	320.50 FL	*- FL
17	1		*RR FLOOR PANEL	Not Affected	1,980.28 FL	*- FL
18	1		*RR FLOOR PANEL COMPARTMENT BOARD	Not Affected	329.40 FL	*- FL
19	1		*RR FLOOR SIDE PANEL LH	Not Affected	689.20 FL	*- FL
20	1		*RR FLOOR PANEL INSULATOR	Not Affected	399.28 FL	*- FL
21	1		*RR FENDER LH	Not Affected	2,094.00 FL	*- FL
22	1		*RR FENDER INNER TRIM LH	Not Affected	784.00 FL	*- FL
23	1		*SER RR NO. PLATE (W/BRACKET)	Not Affected	100.00 FS	*- FS
24	1		*SET RR REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
25	1		*RR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
26	1		*SET RR END PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS
27	1		*SET TAILGATE INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
28	1		*SET TAILGATE REFLECTOR CLIP	Not Necessary	50.00 FS	*- FS
29	1		*SET RR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
30	1		*RR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*RR FENDER SEALANT LH	Not Necessary	80.00 FS	*- FS
32	1		*SET RR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,501.90	1,047.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,722.38	203.56
Total Parts (\$\$)	11,779.52	844.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS	New	300.00	0.00
2	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	2,000.00	200.00
3	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA	New	2,000.00	200.00
4	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	New	300.00	0.00
5	TO TRANSFER TAILGATE COMPONENT PARTS TO NEW TAILGATE	New	200.00	0.00
6	TO REMOVE AND REINSTALL EXHAUST SILENCER FOR NECESSARY REPAIRS	New	250.00	0.00
7	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT	New	200.00	40.00
8	TO REMOVE AND REINSTALL ELECTRICAL WIRING SYSTEM FOR NECESSARY REPAIRS. TO CHECK REAR ELECTRICAL WIRING SYSTEM	New	200.00	0.00
Gross Labour Cost (\$)			5,450.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >