

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21007443/T1UF3N2**Date:** 08/09/2021**REFERENCE**

Insured/Claimant:	KST AUTO RENTAL PTE LTD	Policy No:	0999993604	
Date of Loss:	05/07/2021	Nature of Claim:	OD	Claim No: 7136195281SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK3711E	Engine No:	1KDB037678
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	JTFAT35Y60K215163
Reg. Date:	01/07/2020 (Man. Year: 2020)	Odometer:	31869 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75R15	Rear Tyre Size:	155R12(D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,301.70	3,688.00	1,613.70	30.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,530.00	1,390.00	47.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,221.70	5,218.00	3,003.70	36.53
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	7,221.70	4,218.00	3,003.70	41.59
+ GST 7.00/7.00% (S\$)	505.52	295.26	210.26	41.59
Nett Amount (S\$)	7,727.22	4,513.26	3,213.96	41.59

INSPECTION

Date of Assignment:	08/07/2021		
Date Inspected:	08/07/2021	Inspected At:	Kim Seng Teck Motor Works (HQ) 3021A Ubi Rd 1 #01-42 Singapore 408715
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR (WCP)	Bent	650.00 F	*520.00 F
2	2		*DOOR HINGE (WCP)	Bent	108.00 F	*80.00 F
3	1		*FRONT STEPBOARD (WCP)	Cracked	118.00 F	*105.00 F
4	1		*FRONT CORNER PANEL (WCP)	Missing	118.00 F	*95.00 F
5	1		*FRONT CORNER PANEL GARNISH (WCP)	Not Necessary	55.00 F	*- F
6	1		*FRONT GRILLE (WCP)	Not Necessary	218.00 F	*- F
7	1		*FRONT HEADLAMP (WCP)	Cracked	358.00 F	*310.00 F
8	1		*FRONT BUMPER (WCP)	Deformed	285.00 F	*200.00 F
9	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	152.00 F	*100.00 F
10	1		*AIR CON COIL (WCP)	Bent	1,980.00 F	*1,165.00 F
11	1		*AIR CON FAN MOTOR (WCP)	Cracked	705.00 F	*705.00 F
12	1		*COMPRESSOR OIL	Necessary	35.00 FS	*35.00 FS
13	1		*REFILL GAS	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	4,827.00	3,360.00
+ Margin on L,N Items 10.00/10.00% (S\$)	474.70	328.00
Total Parts (S\$)	5,301.70	3,688.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING & LIGHTING	New	80.00	30.00
2	TO TRANSFER DOOR PARTS TO NEW DOOR	New	180.00	60.00
3	TO DISMANTLE & REFIX CABIN WITH FLOOR FITTING & TRIMING	New	120.00	40.00
4	TO REMOVE & REFIX AIR CON SYSTEM	New	180.00	100.00
5	TO SPRAY PAINT ACCIDENT PORTIONS	New	1,200.00	700.00
6	TO DISMANTLE & REPAIR & REPLACE ACCIDENT AREA & PARTS	New	1,000.00	600.00
7	TOWING FEE	New	160.00	0.00
Gross Labour Cost (\$\$)			2,920.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >