



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 645C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE	BENT	1,283.00	1,283.00
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	412.00	-
1	TAILGATE WEATHERSTRIP	SERVICEABLE	332.00	-
1	TAILGATE EMBLEM "TOYOTA"	NECESSARY	88.00	39.60
1	TAILGATE EMBLEM "PRIUS C"	NECESSARY	76.00	44.00
1	TAILGATE EMBLEM "HYBRID SYNERGY DRIVE"	NECESSARY	76.00	76.00
1	REAR BUMPER	BENT	560.00	560.00
2	REAR BUMPER SIDE RETAINERS RH/LH @\$68.00	SERVICEABLE	136.00	-
1	REAR BUMPER REINFORCEMENT BAR	BENT	512.00	425.10
2	TAIL LAMP RH/LH @\$453.00	SERVICEABLE	906.00	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	211.00	-
1	REAR EXHAUST SYSTEM	TO REPAIR SEE LABOUR	980.00	-
	LESS 25% DISCOUNT		-1,393.00	-606.93
			4,179.00	1,820.77
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER REVERSE SENSOR (SN)	DENTED	280.00	200.00
1	SET REVERSE CAMERA (SN)	SERVICEABLE	450.00	-
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	120.00	40.00
1	SET REAR NUMBER PLATE & GARNISH (SN)	DENTED	60.00	45.00
			910.00	285.00
<b><u>LABOUR</u></b>				
	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE LOCK AND REAR EXHAUST SYSTEM.		1,000.00	500.00
	SPRAY PAINTING ON ACCIDENT AREAS.		1,000.00	600.00
	WIRING CHARGES.		80.00	15.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	50.00
	REMOVE/REFIX REVERSE CAMERA.	NOT NECESSARY	120.00	-
	REMOVE/REFIX REAR EXHAUST.	NOT NECESSARY	120.00	-

Report Ref No. CS/AGI21007446/Kqcn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSFER TAILGATE WINDSCREEN.		200.00	120.00
	TRANSFER TAILGATE COMPONENT.		180.00	60.00
	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS.		180.00	30.00
			3,000.00	1,375.00
GRAND TOTAL			8,089.00	3,480.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,750.00

Report Ref No. CS/AGI21007446/Kqcn2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.