

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21007447/AVCN2**Date:** 01/11/2021**REFERENCE**

Insured/Claimant: CHUE ZHENG YANG Policy No: 7210046282  
Date of Loss: 03/07/2021 Nature of Claim: OD Claim No: 3938566857SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMZ6918Y**  
Make & Model: AUDI E-TRON, SPORTBACK ADV 50 QUATTRO (A) Engine No: HIDDEN  
Reg. Date: 12/05/2021 (Man. Year: 2021) Chassis No: WAUZZZGE9MB030088  
Colour: Grey Odometer: 1710 km  
Engine Capacity: 0 cc  
Market Value/New Car Price: S\$300,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 255/50R20 Rear Tyre Size: 255/50R20  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	22,447.00	13,226.96	9,220.04	41.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,544.00	4,164.00	4,380.00	51.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>30,991.00</b>	<b>17,390.96</b>	<b>13,600.04</b>	<b>43.88</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	30,391.00	16,790.96	13,600.04	44.75
<b>+ GST 7.00/7.00% (S\$)</b>	2,127.37	1,175.37	952.00	44.75
<b>Nett Amount (S\$)</b>	<b>32,518.37</b>	<b>17,966.33</b>	<b>14,552.04</b>	<b>44.75</b>

**INSPECTION**

Date of Assignment: 08/07/2021  
Date Inspected: 07/07/2021 Inspected At: 24 BENOI SECTOR  
SINGAPORE 629857  
REPAIRER: PREMIUM AUTOMOBILES PTE LTD  
Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,724.00 FS	*2,179.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	631.00 FS	*- FS
3	1		*PLASTIC FOAM STRIP	Not Necessary	120.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE LOWER CENTER	Not Necessary	254.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE CENTER	Not Necessary	153.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT CENTER	Cracked	222.00 FS	*177.60 FS
7	1		*FRONT BUMPER CLOSING ELEMENT LOWER CENTER	Not Necessary	210.00 FS	*- FS
8	1		*FRONT AIR INLET RH	Not Necessary	91.00 FS	*- FS
9	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	807.00 FS	*- FS
10	1		*FRONT BUMPER SPOILER RH	Cracked	157.00 FS	*131.60 FS
11	1		*FRONT BUMPER OUTER DUCT RH	Cracked	51.00 FS	*40.48 FS
12	1		*FRONT BUMPER INNER DUCT RH	Cracked	39.00 FS	*31.20 FS
13	1		*FRONT BUMPER TRIM RH	Necessary	58.00 FS	*46.00 FS
14	1		*FRONT BUMPER DUCT RH	Cut	120.00 FS	*95.60 FS
15	1		*FRONT BUMPER GUIDE SECTION RH	Damaged	44.00 FS	*35.12 FS
16	1		*FRONT SENSOR	Not Necessary	0.00 FS	*- FS
17	4		*FRONT SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
18	1		*FRONT FENDER RH	Dented	2,201.00 FS	*1,760.80 FS
19	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	249.00 FS	*- FS
20	1		*FRONT HEADLIGHT SEAL RH	Not Necessary	53.00 FS	*- FS
21	1		*FRONT FENDER BRACKET RH FRONT	Not Necessary	10.00 FS	*- FS
22	1		*FRONT FENDER BRACKET RH CENTRE	Not Necessary	14.00 FS	*- FS
23	1		*FRONT FENDER SUPPORT ELEMENT RH	Not Necessary	40.00 FS	*- FS
24	1		*FRONT FENDER INNER BRACKET RH	Not Necessary	16.00 FS	*- FS
25	1		*FRONT FENDER BRACKET RH	Bent	65.00 FS	*51.92 FS
26	1		*FRONT WHEEL HOUSING LINER RH	Not Necessary	275.00 FS	*- FS
27	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	98.00 FS	*- FS
28	1		*FRONT BUMPER SPOILER RH	Torn	95.00 FS	*75.60 FS
29	1		*FRONT BUMPER BRACKET RH	Not Necessary	77.00 FS	*- FS
30	1		*LED HEADLIGHT RH	Cracked	8,142.00 FS	*6,513.60 FS
31	1		*LED WITH HEAT SINK RH	Not Necessary	1,231.00 FS	*- FS
32	1		*LED HEADLIGHT POWER MODULE RH	Not Necessary	758.00 FS	*- FS
33	1		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM	Not Necessary	236.00 FS	*- FS
34	1		*HOSE FOR HEADLIGHT WASHER SYSTEM	Not Necessary	96.00 FS	*- FS
35	1		*FRONT FENDER INSCRIPTION-E-TRON	Necessary	106.00 FS	*84.80 FS
36	2		*FRONT WHEEL COVER LH/RH	Necessary	1,030.00 FS	*827.20 FS
37	1		*FRONT BUMPER COVER RH	Not Necessary	102.00 FS	*- FS
38	1		*FRONT BUMPER COVER	Not Necessary	105.00 FS	*- FS
39	1		*STICKER FOR WARNING SIGN	Not Necessary	19.00 FS	*- FS
40	1		*SUNDRIES	Necessary	300.00 FS	*18.48 FS
41	1		*LED HEADLIGHT HOSE RH	Not Necessary	29.00 FS	*- FS
42	1		*FRONT FENDER BRACKET-RH (Supplementary)	Bent	133.00 FS	*106.40 FS
43	1		*FRONT REINFORCEMENT-RH (Supplementary)	Cracked	35.00 FS	*29.36 FS
44	1		*FRONT BUMPER BRACKET (Supplementary)	Cracked	430.00 FS	*344.00 FS
45	1		*FRONT BUMPER IMPACT PROTECTION-LOWER (Supplementary)	Torn	807.00 FS	*678.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 22,447.00 13,226.96**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DEACTIVATE AND RE-ACTIVATE HIGH COLTAGE SYSTEM FOR VEHICLE	New	480.00	0.00
2	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
3	TO REMOVE AND TRANSFER RHS HEADLIGHTSS CONTROL UNIT AND POWER MODULE	New	400.00	300.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.TO REPAIR BONNET.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,800.00	1,200.00
5	TO RESPRAY FRONT BUMPER,RHS FRONT BUMPER,LOWER SPOILER,RHS FRONT FENDER.BONNET AND BOTH FRONT WHEEL ARCH TRIMS	New	4,000.00	1,800.00
6	TO CARRY OUT PRE & POST DIAGNOSTIC CHECK	New	384.00	384.00
			<b>Gross Labour Cost (\$\$)</b>	<b>4,164.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >