

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21007449/UPA3Q2**Date:** 05/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210029087
Claimant Vehicle No :	GBA960A	Insured Vehicle No :	SMY7541Z
Date of Loss:	29/06/2021	Nature of Claim:	TP
		Claim No:	9875693297SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA960A	Engine No:	1KD1548590
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y903000158
Reg. Date:	02/02/2007 (Man. Year: 2006)	Odometer:	962090 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Falken 5/5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Falken 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,059.60	6,218.87	11,840.73	65.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,560.00	2,830.00	1,730.00	37.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,619.60	9,048.87	13,570.73	60.00
Approved Total (Overridden) (S\$)		7,200.00		
(S\$)	22,619.60	7,200.00	15,419.60	68.17
+ GST 7.00/7.00% (S\$)	1,583.37	504.00	1,079.37	68.17
Nett Amount (S\$)	24,202.97	7,704.00	16,498.97	68.17
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,455.00		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment:	08/07/2021	
Date Inspected:	08/07/2021	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	8.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*TAILLAMPS	Cracked	593.80 F	*571.00 FL
2	2		*TAILLAMP BRACKETS	Bent	210.00 F	*210.00 FL
3	1		*REAR EXHAUST	Not Necessary	488.20 F	*- FL
4	1		*REAR SPARE TYRE CHAIN & BRACKET	Not Necessary	398.20 F	*- FL
5	1		*REAR LICENCE PLATE BRACKET	Bent	198.50 F	*168.20 FL
6	1		*FRONT PANEL (50%)	Dented / Bent	1,615.10 FS	*807.55 FS
7	1		*FRONT PANEL CENTRE BLACK GARNISH	Scratched	366.50 F	*266.20 FL
8	2		*FRONT CORNER PANELS	Not Necessary	410.00 F	*- FL
9	1		*FRONT CORNER PANEL TOP BLACK GARNISH N/S	Not Necessary	155.10 F	*- FL
10	1		*FRONT DYNA EMBLEM	Necessary	85.00 F	*85.00 FL
11	1		*FRONT WINDSCREEN RUBBER	Necessary	211.10 F	*211.10 FL
12	1		*FRONT TOP NOSE PANEL GARNISH	Dented / Bent	388.20 F	*388.20 FL
13	1		*FRONT GRILLE	Cracked	675.10 F	*675.10 FL
14	1		*FRONT GRILLE LOGO	Necessary	105.00 F	*102.00 FL
15	2		*HEADLAMPS	Cracked	1,810.20 F	*1,566.20 FL
16	1		*FRONT BUMPER (50%)	Bent	488.20 FS	*244.10 FS
17	1		*FRONT CROSS MEMBER	Repair	655.50 F	*- FL
18	1		*FRONT CABIN CROSS MEMBER	Not Necessary	850.10 F	*- FL
19	1		*AIR CON BLOWER	Cracked	1,005.30 F	*1,005.30 FL
20	1		*AIR CON HEATER UNIT	Not Necessary	1,650.00 F	*- FL
21	1		*AIR CON CONDENSER	Not Necessary	1,220.20 F	*- FL
22	1		*FRONT DOOR N/S	Not Necessary	1,715.10 F	*- FL
23	1		*DASHBOARD	Not Necessary	845.20 F	*- FL
24	1		*REAR FREEZER BOX LOCK BAR O/S	Repair	380.00 FS	*- FS
25	1		*REAR LICENCE PLATE	Bent	20.00 FS	*14.00 FS
26	1		*REAR STEP PANEL	Bent	180.00 FS	*180.00 FS
27	1		*1500KG STICKER	Not fitted	80.00 FS	*- FS
28	1		*SET REAR STOPPER	Damaged	200.00 FS	*200.00 FS
29	1		*SET REAR REVERSE BUZZER	Cracked	280.00 FS	*150.00 FS
30	1		*REAR END ALUMINIUM PLATE	Badly Dented	680.00 FS	*680.00 FS
31	1		*SET ALUMINIUM RIVET	Not Necessary	80.00 FS	*- FS
32	1		*FRONT LICENCE PLATE (50%)	Bent	20.00 FS	*7.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,059.60	7,530.95
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,312.08

Total Parts (\$\$)	18,059.60	6,218.87
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACING REVERSE BUZZER	New	80.00	40.00
3	TO DISMANTLE & REFIX REAR EXHAUST	New	80.00	0.00
4	TO REFILL AIR CON GAS	New	100.00	100.00
5	TO DISMANTLE & REFIX FRONT WINDSCREEN	New	150.00	60.00
6	TO DISMANTLE & REFIX FRONT DASHBOARD	New	300.00	200.00
7	TO DISMANTLE & REPLACING AIR CON BLOWER	New	100.00	50.00
8	TO SPRAY RUST PROOFING	New	100.00	50.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	1,300.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,000.00
Gross Labour Cost (\$\$)			4,560.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >