

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21007454/UPS3Q2**Date:** 11/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900158213
<b>Claimant Vehicle No :</b>	SKT4816B	<b>Insured Vehicle No :</b>	SMP1370L
Date of Loss:	07/07/2021	Nature of Claim:	TP
		Claim No:	2618637147SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKT4816B</b>	Engine No:	QR25078617L
Make & Model:	NISSAN ELGRAND, 2.5 Highway Star (A)	Chassis No:	JN1TBAE52Z0802267
Reg. Date:	11/06/2015 (Man. Year: 2014)	Odometer:	196372 km
Colour:	White		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	25,058.55	11,366.05	13,692.50	54.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,000.00	2,410.00	2,590.00	51.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>30,058.55</b>	<b>13,776.05</b>	<b>16,282.50</b>	<b>54.17</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>11,000.00</b>		
<b>(S\$)</b>	30,058.55	11,000.00	19,058.55	63.40
<b>+ GST 7.00/7.00% (S\$)</b>	2,104.10	770.00	1,334.10	63.40
<b>Nett Amount (S\$)</b>	<b>32,162.65</b>	<b>11,770.00</b>	<b>20,392.65</b>	<b>63.40</b>
<b>+ Car Rental (5.0 x S\$150.00/day) (S\$)</b>		750.00		
<b>(S\$)</b>		12,520.00		
<b>Liabile Amount (80.00%) (S\$)</b>		<b>10,016.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>10,018.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>10,000.00</b>		

**INSPECTION**

Date of Assignment:	08/07/2021		
Date Inspected:	08/07/2021	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days		

---

**Adjuster:** MARCUS CHUA

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Repair	1,680.20 FL	*- FL
2	1		*FRONT DOOR OUTER PROTECTOR O/S	Grazed / Jammed	785.40 FL	*722.10 FL
3	1		*SLIDING DOOR O/S	Badly Dented	1,680.90 FL	*1,420.90 FL
4	1		*SLIDING DOOR OUTER PROTECTOR O/S	Distorted	694.90 FL	*694.10 FL
5	1		*SLIDING DOOR OUTER HANDLE O/S	Not Necessary	385.80 FL	*- FL
6	1		*SLIDING DOOR FRAME BLACK GARNISH O/S	Necessary	166.20 FL	*118.00 FL
7	1		*SLIDING DOOR INNER LOCK O/S	Shorted	688.40 FL	*433.20 FL
8	1		*SLIDING DOOR INNER RUBBER O/S	Necessary	271.20 FL	*271.20 FL
9	1		*SLIDING DOOR INNER TRIM BOARD O/S	Deformed / Torn	3,552.10 FL	*3,052.10 FL
10	1		*SLIDING GLASS REGULATOR & MOTOR O/S	Bent / Jammed	850.20 FL	*650.50 FL
11	1		*SLIDING DOOR LOWER ROLLER BRACKET O/S	Bent	645.50 FL	*288.20 FL
12	1		*SLIDING DOOR LOWER ROLLER MOTOR O/S	Serviceable	568.10 FL	*- FL
13	1		*SLIDING DOOR LOCK AUTUATOR O/S	Jammed	488.30 FL	*450.50 FL
14	1		*REAR SHOCK ABSORBER O/S	Serviceable	562.10 FL	*- FL
15	1		*REAR LOWER ARM O/S	Twisted	1,225.30 FL	*845.20 FL
16	1		*REAR TRAILING ARM O/S	Bent	561.90 FL	*485.50 FL
17	1		*REAR TORSION ARM O/S	Twisted	499.20 FL	*319.20 FL
18	1		*REAR WHEEL HUB BEARING O/S	Damaged	688.50 FL	*580.10 FL
19	1		*REAR CROSS MEMBER	Not Necessary	1,822.00 FL	*- FL
20	1		*REAR FENDER O/S	Repair	1,845.30 FL	*- FL
21	1		*REAR FENDER GLASS O/S	Not Necessary	1,200.00 FL	*- FL
22	1		*REAR WHEEL ARCH PANEL O/S	Dented / Bent	544.90 FL	*505.20 FL
23	1		*REAR BUMPER	Deformed / Torn	2,721.60 FL	*848.50 FL
24	1		*REAR BUMPER REFLECTOR O/S	Not Necessary	35.00 FL	*- FL
25	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	45.50 FL	*- FL
26	1		*TAILLAMP O/S	Not Necessary	612.20 FL	*- FL
27	1		*TAILLAMP LOWER GARNISH O/S	Not Necessary	488.80 FL	*- FL
28	1		*REAR FENDER GLASS SEALANT O/S	Not Necessary	50.00 FS	*- FS
29	1		*REAR SPORT RIM 18 INCH	Cut / Bent	1,800.00 FS	*800.00 FS
30	1		*REAR TYRE O/S	Serviceable	380.00 FS	*- FS
31	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>27,589.50</b>	<b>12,534.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	2,530.95	1,168.45
<b>Total Parts (\$\$)</b>	<b>25,058.55</b>	<b>11,366.05</b>

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX FRONT DOOR MECHANISM	New	100.00	0.00
4	TO DISMANTLE & REFIX SLIDING DOOR MECHANISM	New	100.00	80.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	100.00
6	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	New	380.00	120.00
7	TO DISMANTLE & REFIX REAR FENDER GLASS	New	120.00	0.00
8	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
9	TO RESET & REPROGRAMME SYSTEM	New	150.00	0.00
10	TO SPRAY RUST RPOOFING	New	150.00	60.00
11	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	800.00
12	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,100.00
			<b>Gross Labour Cost (\$)</b>	<b>5,000.00</b>
				<b>2,410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >