

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/AIG21007460/UPA3Q2

Date:

18/08/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100076668

Claimant Vehicle No : SML95J**Insured Vehicle No :**

SJE9257Y

Date of Loss: 07/07/2021

Nature of Claim:

TP

Claim No:

4667776050SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SML95J**

Make & Model: PORSCHE MACAN II, 2.0 PDK E6 (A)

Engine No: 014596

Reg. Date: 12/06/2019 (Man. Year: 2018)

Chassis No: WP1ZZZ95ZKLB03930

Colour: White

Odometer: 21629 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18

Rear Tyre Size:

255/55 R18

Front Left Side: Hankook 7 mm

Rear Left Side:

Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side:

Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,603.00	6,504.30	1,098.70	14.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	2,080.00	1,600.00	43.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,283.00	8,584.30	2,698.70	23.92
+ GST 7.00/7.00% (S\$)	789.81	600.90	188.91	23.92

Nett Amount (\$)	12,072.81	9,185.20	2,887.61	23.92
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment:	22/07/2021		
Date Inspected:	22/07/2021	Inspected At:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	3.0 days		

Adjuster:	MARCUS CHUA	Manager:	CHEW HSIAO TONG
------------------	-------------	-----------------	-----------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR ASSY LH	Badly Dented	2,625.00 F	*2,625.00 FL
2	1		*FRONT DOOR WEATHERSTRIP LH	Necessary	312.00 F	*312.00 FL
3	1		*FRONT DOOR GARNISH (LH)	Distorted	746.00 F	*746.00 FL
4	1		*REAR DOOR ASSY LH	Badly Dented	2,325.00 F	*2,325.00 FL
5	1		*REAR DOOR WEATHERSTRIP LH	Necessary	312.00 F	*312.00 FL
6	1		*REAR DOOR GARNISH LH	Torn	748.00 F	*748.00 FL
7	1		*REAR DOOR STONE GUARD LH	Scratched	159.00 F	*159.00 FL
8	1		*RUNNING BOARD SKIRT LH	Serviceable	376.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	7,603.00	7,227.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	722.70
Total Parts (\$)	7,603.00	6,504.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CUT OUT RENEW ,KNOCKING & WELDING FRONT DOOR ASSY LH ,REAR DOOR ASSY RH ,REMOVE & INSTALL ALL DAMAGE PARTS & REALIGN BODY	New	980.00	500.00
2	TUFF -KOTE ON DAMAGE PARTS	New	80.00	60.00
3	REMOVE & INSTALL FRONT & REAR DOOR BOARD ,LOCK & ETC	New	380.00	300.00
4	SPRAY PAINTING ON DAMAGE PARTS	New	1,880.00	1,100.00
5	CHECK DOOR WIRING AFTER REPAIRS	New	60.00	20.00
6	DIAGNOSTIC & RESET	New	300.00	100.00
Gross Labour Cost (\$\$)			3,680.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >