

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007468/KGA3Q2
Date: 30/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900242496
Claimant Vehicle No :	SLH2652X	Insured Vehicle No :	SCW99J
Date of Loss:	07/07/2021	Nature of Claim:	TP
		Claim No:	4631834109SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH2652X		
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Engine No:	2ZR1849746
Reg. Date:	28/10/2016 (Man. Year: 2016)	Chassis No:	JTDGG20W80J005757
Colour:	Metallic Pearl White	Odometer:	195455 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Presa 2 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Presa 2 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,847.12	2,467.42	2,379.70	49.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	940.00	860.00	47.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,647.12	3,407.42	3,239.70	48.74
+ GST 7.00/7.00% (S\$)	465.30	238.52	226.78	48.74

Nett Amount (S\$)	7,112.42	3,645.94	3,466.48	48.74
		+ Car Rental (5.0 x S\$130.00/day) (S\$)	650.00	
		+ Doc/Search Fee (S\$)	7.45	
		Nett Liability (S\$)	4,303.39	

INSPECTION

Date of Assignment: 08/07/2021

Date Inspected: 12/07/2021

Estimated Period of Repair: 5.0 days

Inspected At:

BCC Automotive Pte Ltd (Sin Ming)
 Blk 1 Sin Ming Industrial Estate, Sector C #01-101
 Singapore 575636

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	977.80 FL	*- FL
2	1		*BONNET HINGE	Repair	98.00 FL	*- FL
3	1		*BONNET TOP SUPPORT PANEL	Repair	950.00 FL	*- FL
4	1		*RADIATOR SUPPORT PANEL (PLASTIC)	Serviceable	280.00 FL	*- FL
5	1		*TOYOTA EMBLEM	Not Necessary	89.00 FL	*- FL
6	1		*BONNET GRILLE	Cracked	415.00 FL	*286.20 FL
7	1		*FRONT RH HEAD LAMP	Mtg Cracked	1,265.70 FL	*1,265.70 FL
8	1		*FRONT BUMPER	Cracked	650.00 FL	*565.80 FL
9	1		*FRONT BUMPER RH RETAINER	Distorted	72.00 FL	*72.00 FL
10	1		*FRONT BUMPER END PANEL	Repair	350.00 FL	*- FL
11	1		*FRONT BUMPER CENTER GRILLE (PLASTIC)	Cracked	128.00 FL	*128.00 FL
12	1		*FRONT RH FOG LAMP	Mtg Cracked	405.00 FL	*343.20 FL
13	1		*FRONT RH FOG LAMP SIDE GRILLE	Cracked	98.00 FL	*98.00 FL
14	10		*CLIPS	Necessary	80.00 FL	*80.00 FL
15	1		*FRONT NUMBER PLATE W/FRAME	Bent	60.00 FS	*45.00 FS
16	1		*VEHICLE GRAPHIC	Necessary	250.00 FS	*150.00 FS
17	1		*FRONT RH FOG LAMP SUPPORT BRACKET	Cracked	85.00 FL	*85.00 FL
18	1		*FRONT BUMPER ABSORBER	Cracked	106.00 FL	*106.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,359.50	3,224.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,512.38	757.48
Total Parts (\$\$)	4,847.12	2,467.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT THE AFFECTED AREA	New	800.00	500.00
2	TO SPRAY PAINT ON THE AFFECTED AREA	New	1,000.00	440.00
Gross Labour Cost (S\$)			1,800.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >