

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007469/EVCN2**Date:** 24/08/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00121972101		
Claimant Vehicle No :	SKZ4579D	Insured Vehicle No :	SMC3139U		
Date of Loss:	06/07/2021	Nature of Claim:	TP	Claim No:	SNM21D203766/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ4579D		
Make & Model:	TOYOTA SIENTA, 1.5 G CVT ABS D/AIRBAG 2WD 5DR (A)	Engine No:	1NZR320763
Reg. Date:	22/01/2016 (Man. Year: 2015)	Chassis No:	NHP1707005717
Colour:	White	Odometer:	88889 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,007.10	5,306.10	1,701.00	24.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	1,710.00	480.00	21.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,197.10	7,016.10	2,181.00	23.71
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	9,197.10	5,500.00	3,697.10	40.20
+ GST 7.00/7.00% (S\$)	643.80	385.00	258.80	40.20
Nett Amount (S\$)	9,840.90	5,885.00	3,955.90	40.20

INSPECTION

Date of Assignment:	12/07/2021		
Date Inspected:	09/07/2021	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	7.0 days		

Adjuster: VERON CHEN**Manager:** CHEN TSUE YEE*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Aug 2021)

Parts: M1-MPV TOYOTA SIENTA 1.5 G CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKZ4579D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	1,231.90 FL	*1,152.00 FL
2	1		*REAR BOOT LOGO	Necessary	76.50 FL	*76.50 FL
3	1		*REAR BOOT EMBLEM	Necessary	79.70 FL	*79.70 FL
4	1		*REAR BOOT LOCK	Bent	467.60 FL	*318.00 FL
5	1		*REAR BOOT LOCK COVER	Crushed	69.30 FL	*69.30 FL
6	1		*REAR BOOT LOCK CATCH	Not Necessary	28.20 FL	*- FL
7	1		*REAR BOOT RUBBER	Crushed	372.80 FL	*372.80 FL
8	2		*REAR BOOT HINGES	Not Necessary	156.40 FL	*- FL
9	1		*REAR BOOT DAMPLE	Not Necessary	290.80 FL	*- FL
10	1		*REAR BOOT INNER TRIM	Not Necessary	561.60 FL	*- FL
11	1		*REAR BOOT LAMP RH	Cut	371.70 FL	*371.70 FL
12	1		*REAR WINDSCREEN MOULDING	Necessary	273.60 FL	*112.00 FL
13	1		*REAR LAMP RH	Broken	395.60 FL	*395.60 FL
14	2		*REAR LAMP GROMMET	Necessary	15.00 FL	*15.00 FL
15	1		*REAR END PANEL	Dented	783.80 FL	*783.80 FL
16	1		*REAR END PANEL TRIM	Crushed	175.50 FL	*175.50 FL
17	1		*REAR FLOOR TOP COVER	Crushed	561.40 FL	*561.40 FL
18	1		*REAR FLOOR TRIM COVER	Not Necessary	371.30 FL	*- FL
19	1		*REAR FENDER INNER TRIM RH	Crushed	781.40 FL	*713.00 FL
20	1		*REAR BUMPER	Dented	874.60 FL	*788.00 FL
21	1		*REAR BUMPER PROTECTOR CTR	Crushed	298.20 FL	*229.00 FL
22	1		*REAR BUMPER PROTECTOR RH	Cut	186.70 FL	*186.70 FL
23	1		*REAR BUMPER TOW COVER	Not Necessary	28.90 FL	*- FL
24	1		*REAR BUMPER REFLECTOR RH	Crushed	121.20 FL	*85.00 FL
25	1		*REAR BUMPER SIDE SHIELD RH	Not Necessary	94.30 FL	*- FL
26	1		*REAR BUMPER BRACKET RH	Broken	78.20 FL	*78.20 FL
27	10		*REAR BUMPER CLIPS	Necessary	35.00 FL	*30.00 FL
28	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
29	1		*REAR BUMPER SENSOR	Shorted	220.00 FS	*200.00 FS
30	1		*KEY LESS SENSOR	Broken	161.60 FL	*161.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,242.80	6,994.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,235.70	1,688.70
Total Parts (\$\$)	7,007.10	5,306.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT & WELD REAR END PANEL,TO REPAIR REAR FLOOR PANEL,REAR FENDER RH,REAR CHASSIS MEMBER.TO REMOVE & REFIX DAMAGED PARTS,STRAIGHTEN AND REALIGN AFFECTED AREAS	New	840.00	700.00
2	TO SPRAY AFFECTED AREAS,REAR BOOT,END PANEL,REAR FLOOR PANEL,REAR FENDER,REAR BUMPER AND AFFECTED AREAS	New	850.00	750.00
3	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	180.00	120.00
4	TO REMOVE & REFIX REAR BOOT MECHANISM CHECK & TEST WIPER MOTOR & CENTRE LOCKING SYSTEM	New	80.00	30.00
5	TO REMOVE & REFIX THIRD ROLL CUSHION,REAR SAFETY BELT,SIDE COVER,SIDE GARNISH AND OTHER ATTACHMENT PARTS	New	100.00	50.00
6	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE	New	60.00	30.00
7	TO RUST PROOF AFFECTED AREAS	New	80.00	30.00
Gross Labour Cost (\$\$)			2,190.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >