



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 430E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR LH	TO REPAIR SEE LABOUR	1,025.60	-
1	REAR FENDER LH	DENTED	996.80	996.80
1	REAR FENDER INNER SHIELD LH	DISTORTED	145.10	110.00
1	REAR BUMPER	BROKEN	854.10	580.30
1	REAR BUMPER SIDE RETAINER LH	NECESSARY	36.10	30.00
1	REAR SHOCK ABSORBER LH	NOT DAMAGED	265.30	-
1	REAR WHEEL BEARING LH	JAMMED	165.10	110.00
1	REAR AXLE	NOT DAMAGED	1,325.80	-
	LESS 20% DISCOUNT		-962.78	-365.42
			3,851.12	1,461.68
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TYRE LH (SN)	NOT DAMAGED	250.00	-
1	REAR TYRE RIM LH (SN)	CUT	566.00	300.00
1	REAR FENDER SEALANT LH (SN)	NECESSARY	30.00	30.00
			846.00	330.00
	<u>LABOUR</u>			
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE "PARTS REPAIR" COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR LH.		810.00	600.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT/MATERIAL (3 PANELS).		700.00	400.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		20.00	20.00
	REMOVE AND REPLACE REAR UNDERCARRIAGE WORKS LH.		225.00	120.00
	REMOVE AND REFIX INNER TRIM TO FACILITATE THE REPLACEMENT OF REAR FENDER LH.		67.50	45.00
	REMOVE AND REFIX FUEL TANK, PIPES TO FACILITATE THE REPAIR WORKS.		67.50	45.00
	CONDUCT WATER LEAK TEST FOR REAR PORTION ASSOCIATED REPAIR WORKS.	NOT NECESSARY	45.00	-

Report Ref No. CS3/AIG21005570/Bvf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING AND BULB CHCKING.	NOT NECESSARY	36.00	-
			1,971.00	1,230.00
	GRAND TOTAL		6,668.12	3,021.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS3/AIG21005570/Bvf3e2-1

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.