

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21007473/AUCE2

**Date:** 18/11/2021

### REFERENCE

Insured/Claimant:	YEO TSIN POH	Policy No:	2070032103		
Date of Loss:	02/07/2021	Nature of Claim:	OD	Claim No:	4287734710SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDS351P	Engine No:	CZD891531
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF37L1076863
Reg. Date:	20/03/2020 (Man. Year: 2020)	Odometer:	20700 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$145,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,485.00	9,259.92	5,225.08	36.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,252.00	3,852.00	3,400.00	46.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>21,737.00</b>	<b>13,111.92</b>	<b>8,625.08</b>	<b>39.68</b>
<b>- Excess (S\$)</b>	<b>3,400.00</b>	<b>3,400.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>18,337.00</b>	<b>9,711.92</b>	<b>8,625.08</b>	<b>47.04</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,283.59</b>	<b>679.83</b>	<b>603.76</b>	<b>47.04</b>
<b>Nett Amount (S\$)</b>	<b>19,620.59</b>	<b>10,391.75</b>	<b>9,228.84</b>	<b>47.04</b>

### INSPECTION

Date of Assignment:	09/07/2021		
Date Inspected:	08/07/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** ADRIAN LING

**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,008.00 FS	*806.40 FS
2	1		*FRONT BUMPER CONNECTING PIECE	Not Necessary	145.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT LH	Not Necessary	59.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Cracked	217.00 FS	*173.20 FS
5	1		*FRONT BUMPER GRILLE - LH	Cut	110.00 FS	*88.00 FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Deformed	383.00 FS	*306.40 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	153.00 FS	*122.00 FS
9	1		*RADIATOR GRILLE	Cut	1,433.00 FS	*1,146.40 FS
10	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
11	1		*FRONT BUMPER GUIDE SECTION LH	Cracked	39.00 FS	*30.48 FS
12	1		*FOAM FILLER PIECE	Not Necessary	102.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	916.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Not Necessary	123.00 FS	*- FS
15	1		*AIRCOND STICKER	Not Necessary	8.00 FS	*- FS
16	1		*FRONT PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
			(NPA)			
17	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
18	1		*SIGNAL HORN LH	Not Necessary	137.00 FS	*- FS
19	1		*HORN BRACKET LH	Not Necessary	137.00 FS	*- FS
20	1		*FRONT FENDER LH	Buckled	1,286.00 FS	*1,028.80 FS
21	1		*FRONT FENDER ATTACHMENT PARTS LH	Not Necessary	63.00 FS	*- FS
22	1		*FRONT FENDER BRACKET LH	Damaged	32.00 FS	*24.88 FS
23	1		*FRONT FENDER BRACE LH	Bent	88.00 FS	*69.76 FS
24	1		*FRONT WHEEL HOUSING LINER LH	Not Necessary	240.00 FS	*- FS
25	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS LH	Not Necessary	101.00 FS	*- FS
26	1		*FRONT FENDER COVER	Not Necessary	16.00 FS	*- FS
27	1		*HEADLIGHT MOUNTING - LH	Cracked	118.00 FS	*94.40 FS
28	1		*LED HEADLIGHT - LH	Cut	5,589.00 FS	*4,471.20 FS
29	1		*LIFT CYLINDER HOSE H	Not Necessary	80.00 FS	*- FS
30	2		*FRONT WHEEL ARCH COVER LH / RH	N/S Cut / O/S Necessary	536.00 FS	*428.80 FS
31	1		*RADIATOR AIR GUIDE LH	Not Necessary	38.00 FS	*- FS
32	1		*RADIATOR AIR GUIDE UPPER	Not Necessary	42.00 FS	*- FS
33	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
34	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
35	1		*LIFT CYLINDER LH	Not Necessary	210.00 FS	*- FS
36	1		*FRONT DOOR COVER - LH	Cut	268.00 FS	*214.40 FS
			(Supplementary)			

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 14,485.00 9,259.92

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL / TRIM. TO REMOVE AND REINSTALL LHS SIDE MIRROR ASSY TO FACILITATE RESPRAY OF FRONT DOOR (Supplementary)	New	280.00	280.00
7	TO RESPRAY LHS FRONT DOOR (Supplementary)	New	1,000.00	550.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,252.00</b>	<b>3,852.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >