

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21007477/EVF3E2

Date: 13/09/2021

REFERENCE

Insured/Claimant:	TAN KOK KIANG	Policy No:	2100505876		
Date of Loss:	08/07/2021	Nature of Claim:	OD	Claim No:	3142789401SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFH3399S	Engine No:	G4FGGH653885
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFZ411MH5676707
Reg. Date:	31/03/2017 (Man. Year: 2016)	Odometer:	56473 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$54,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,336.82	6,182.80	3,154.02	33.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,020.00	4,070.00	1,950.00	32.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,356.82	10,252.80	5,104.02	33.24
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	14,856.82	9,752.80	5,104.02	34.35
+ GST 7.00/7.00% (S\$)	1,039.98	682.70	357.28	34.35
Nett Amount (S\$)	15,896.80	10,435.50	5,461.30	34.35

INSPECTION

Date of Assignment:	09/07/2021	
Date Inspected:	09/07/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, LH	Cut	1,707.00 FL	*1,707.00 FL
3	1		*LAMP ASSY-HEAD, RH	Cut	1,707.00 FL	*1,707.00 FL
4	1		*PANEL ASSY-HOOD	Dented	1,384.00 FL	*1,384.00 FL
5	1		*HINGE ASSY-HOOD, LH	Bent	34.00 FL	*34.00 FL
6	1		*HINGE ASSY-HOOD, RH	Bent	34.00 FL	*34.00 FL
7	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
8	1		*COVER-FR BUMPER	Dented	633.00 FL	*633.00 FL
9	1		*CAP-FRONT HOOK	Not Necessary	9.00 FL	*- FL
10	1		*MOULDING-FRT BPR LICENSE PLATE	Not Necessary	18.00 FL	*- FL
11	1		*LIP ASSY-FRONT BUMPER	Not Necessary	55.00 FL	*- FL
12	1		*GRILLE ASSY-RADIATOR	Broken	328.00 FL	*328.00 FL
13	1		*GARNISH-RADIATOR GRILLE, UPR	Crushed	54.00 FL	*54.00 FL
14	1		*STRIP ASSY-FR BUMPER UPR	Cut	29.00 FL	*29.00 FL
15	1		*MOULDING-FRONT BUMPER A/INTAKE	Not Necessary	91.00 FL	*- FL
16	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	84.00 FL	*- FL
17	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
18	1		*RAIL ASSY-FR BUMPER	Not Necessary	496.00 FL	*- FL
19	1		*BRACKET-FR BUMPER SIDE MTG, LH	Not Necessary	13.00 FL	*- FL
20	1		*BRACKET-FR BUMPER SIDE MTG, RH	Not Necessary	13.00 FL	*- FL
21	1		*WIRING HARNESS-FR BUMPER	Not Necessary	237.00 FL	*- FL
22	4		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	708.00 FL	*- FL
23	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
24	1		*GLASS-WINDSHIELD	Broken	956.00 FL	*956.00 FL
25	1		*MOULDING-WINDSHIELD GLASS	Necessary	62.00 FL	*62.00 FL
26	1		*BRACKET, IU ADHESIVE	Necessary	26.00 FS	*26.00 FS
27	1		*CONDENSER ASSY-COOLER	Not Necessary	681.00 FL	*- FL
28	1		*RADIATOR ASSY	Not Necessary	546.00 FL	*- FL
29	1		*BLOWER ASSY	Not Necessary	623.00 FL	*- FL
30	1		*LATCH ASSY-HOOD	Not Necessary	65.00 FL	*- FL
31	1		*PAD-HOOD INSULATING	Not Necessary	141.00 FL	*- FL
32	11		*CLIP-HOOD INSULATING PAD MTG	Not Necessary	11.00 FL	*- FL
33	1		*COOLANT (4L)	Not Necessary	26.00 FN	*- FN
34	10		*CLIP (Supplementary)	Necessary	10.00 FL	*10.00 FL
35	2		*STOPPER-RR WINDOW GLASS (Supplementary)	Necessary	8.00 FL	*8.00 FL
36	6		*RETAINER-COWL TOP COVER MTG (Supplementary)	Necessary	18.00 FL	*18.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	11,658.00	7,717.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,315.20	1,534.20
- Nett Item Discount on N Items 23.00/23.00% (\$\$)	5.98	0.00
Total Parts (\$\$)	9,336.82	6,182.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FR BUMPER, FR SUPPORT & BONNET. REPAIR LHF FENDER, LHF A PILLAR, RHF FENDER & RHF A PILLAR	New	2,400.00	800.00
2	RESPRAY FR BUMPER, BONNET, LHF FENDER, LHF A PILLAR, RHF FENDER & RHF A PILLAR	New	2,100.00	2,100.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	0.00
4	TOP UP AC GAS	New	80.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	RENEW FR WINDSCREEN GLASS	New	240.00	240.00
8	SUPPLY FR WINDSCREEN SEALANT	New	80.00	80.00
9	SUPPLY FR NUMBER PLATE WITH CASING	New	50.00	0.00
10	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
11	SUPPLY BODY PNL SEALANT	New	60.00	40.00
12	INSTALL FR WINDSCREEN SOLAR FILM	New	280.00	220.00
13	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	400.00	400.00
Gross Labour Cost (\$\$)			6,020.00	4,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >