

ASS. REC. BY:

Steve

CS/AIG 2100 7477/EV F3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

SIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

NV-548
PV-42,917
NV-11,083

Date/Time, File, Pass to:

: Prel. Report

: Final Report

Date/Time, File Return to:

Date/Time, File Return to:

Date/Time, File Return to:

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Other

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng No:

Ch No:

Gen. Cond: Good / Fair / Poor / Bump

Steering: In order / Jammed / Locked / Burnt or

Brakes: In order / Jammed / Locked / Burnt or

Mod: Nil / Bump / STD / Air or

Tyre Size:

F:

R:

B3 / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PER / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof top or

The U/C / Chassis frame / Body Structure affected due to collision

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS

Phone

Others

TOTAL

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Inve (\$

: Weekend (\$



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /TAN KOK KIANG Reg No/Reg Date SFH3399S / 31/03/201 Date In/Mileage / 0 Chassis No KNAFZ411MH5676707 Engine No G4FGGH653885 Make/Model KIA/FORTE K3 1.6 A SX HADQ Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	09/07/2021/ 09:07	BLE	261 / Edwin Caina	35774			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								800 2400.00
RENEW FR BUMPER , FR SUPPORT & BONNET					2 X 494			
REPAIR LHF FENDER , LHF A PILLAR , RHF FENDER & RHF A PILLAR								2100.00 ✓
E PNT98000								100.00
RESPRAY FR BUMPER , BONNET , LHF FENDER , LHF A PILLAR , RHF FENDER & RHF A PILLAR					6 X 350			
E PNT88000								80.00
REMOVE & REFIT AC COND & RADIATOR								
M SUNDRY								30.00 ✓
TOP UP AC GAS								
A 54900099								120.00 ✓
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								
A 10028901								240.00 ✓
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
E PNT88000								280.00
RENEW FR WINDSCREEN GLASS								270
M SUNDRY								80.00 ✓
INSTALL FR WINDSCREEN SOLAR FILM								
M SUNDRY								50.00
SUPPLY FR WINDSCREEN SEALANT								X
M SUNDRY								80.00
SUPPLY FR NUMBER PLATE WITH CASING								40
M SUNDRY								60.00
APPLY ANTI CORROSION ON AFFECTED AREAS								40
M SUNDRY								30.00
SUPPLY BODY PNL SEALANT								20
M SUNDRY								
Sundries								
M LAMP ASSY-HEAD,LH	/		CUT		1.00	1707.00	20.00	1365.60
M LAMP ASSY-HEAD,RH	/		CUT		1.00	1707.00	20.00	1365.60
M PANEL ASSY-HOOD	/		CO		1.00	1384.00	20.00	1107.20
M HINGE ASSY-HOOD,LH	/		RT		1.00	34.00	20.00	27.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for replacement of windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



LE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /TAN KOK KIANG Reg No/Reg Date SFH3399S / 31/03/201 Date In/Mileage / 0 Chassis No KNAFZ411MH5676707 Engine No G4FGGH653885 Make/Model KIA/FORTE K3 1.6 A SX HADQ Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	09/07/2021/ 09:07	BLE	261 / Edwin Caina	35774			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	HINGE ASSY-HOOD,RH	BT			1.00	34.00	20.00	27.20
M	CARRIER ASSY-FRONT END MODULE				1.00	675.00	20.00	540.00
M	COVER-FR BUMPER	00			1.00	633.00	20.00	506.40
M	CAP-FRONT HOOK	X			1.00	9.00	20.00	7.20
M	MOULDING-FRT BPR LICENSE PLATE	X			1.00	18.00	20.00	14.40
M	LIP ASSY-FRONT BUMPER	X			1.00	55.00	20.00	44.00
M	GRILLE ASSY-RADIATOR	GR			1.00	328.00	20.00	262.40
M	GARNISH-RADIATOR GRILLE,UPR	CRU			1.00	54.00	20.00	43.20
M	STRIP ASSY-FR BUMPER UPR	CUT			1.00	29.00	20.00	23.20
M	MOULDING-FRONT BUMPER A/INTAKE	X			1.00	91.00	20.00	72.80
M	ABSORBER-FRONT BUMPER ENERGY	X			1.00	84.00	20.00	67.20
M	STIFFNER-FR BPR LWR	X			1.00	114.00	20.00	91.20
M	RAIL ASSY-FR BUMPER	X			1.00	496.00	20.00	396.80
M	BRACKET-FR BUMPER SIDE MTG,LH				1.00	13.00	20.00	10.40
M	BRACKET-FR BUMPER SIDE MTG,RH				1.00	13.00	20.00	10.40
M	WIRING HARNESS-FR BUMPER	X			1.00	237.00	20.00	189.60
M	ULTRASONIC SENSOR ASSY-P.A.S	X			4.00	177.00	20.00	566.40
M	ORNAMENT-KIA NO.115	ACC			1.00	32.00	20.00	25.60
M	GLASS-WINDSHIELD	GR			1.00	956.00	20.00	764.80
M	MOULDING-WINDSHIELD GLASS	ACC			1.00	62.00	20.00	49.60
M	BRACKET, IU ADHESIVE	ACC			1.00	26.00	00.00	26.00
M	CONDENSER ASSY-COOLER				1.00	681.00	20.00	544.80
M	RADIATOR ASSY				1.00	546.00	20.00	436.80
M	BLOWER ASSY				1.00	623.00	20.00	498.40
M	LATCH ASSY-HOOD				1.00	65.00	20.00	52.00
M	PAD-HOOD INSULATING	X			1.00	141.00	20.00	112.80
M	CLIP-HOOD INSULATING PAD MTG	X			11.00	1.00	20.00	8.80
M	COOLANT (4L)				1.00	26.00	23.00	20.02

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: 9/7/21, 11:30am

DATE: 09-14-21

REMARKS: EXHIBIT - 1

SURVEYOR NAME: Steve CLKK
 SURVEYOR SIGNATURE: 9/7/21, 11-30am
 DATE: 00-11-11
 REMARKS: EXTRA - ?

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis.
 Authorized signatory and company stamp

P/P, My Bel Sy
6 dys

Nett 14,928.02
 7% GST on 14928.02 1044.96
Total Payable 15,972.98

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.