



CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/TAN KOK KIANG
	Reg No/Reg Date	SFH3399S / 31/03/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MH5676707
	Engine No	G4FGGH653885
	Make/Model	KIA/FORTE K3 1.6 A SX HADQ
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	09/07/2021/ 09:07	BLE	261 / Edwin Caina	35774	Qty	Unit Price	Disc%
Description of Goods / Services								Amount
E PNT88000 / RENEW FR BUMPER, FR SUPPORT & BONNET						2 x 474		2100.00
REPAIR LHF FENDER, LHF A PILLAR, RHF FENDER & RHF A PILLAR								2100.00
E PNT98000 RESPRAY FR BUMPER, BONNET, LHF FENDER, LHF A PILLAR, RHF FENDER & RHF A PILLAR						6 x 350		100.00
E PNT88000 REMOVE & REFIT AC COND & RADIATOR								80.00
M SUNDRY TOP UP AC GAS								30.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								240.00
E PNT88000 RENEW FR WINDSCREEN GLASS						170		280.00
M SUNDRY INSTALL FR WINDSCREEN SOLAR FILM								80.00
M SUNDRY SUPPLY FR WINDSCREEN SEALANT						X		50.00
M SUNDRY SUPPLY FR NUMBER PLATE WITH CASING						40		80.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS						40		60.00
M SUNDRY SUPPLY BODY PNL SEALANT						20		30.00
M SUNDRY Sundries						1.00	1707.00	20.00
M LAMP ASSY-HEAD,LH						1.00	1707.00	20.00
M LAMP ASSY-HEAD,RH						1.00	1384.00	20.00
M PANEL ASSY-HOOD						1.00	34.00	20.00
M HINGE ASSY-HOOD,LH								27.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name	/TAN KOK KIANG
MOTOR CLAIM DEPARTMENT	Reg No/Reg Date	SFH3399S / 31/03/201
78 SHENTON WAY #09-16	Date In/Mileage	/ 0
AIG BUILDING	Chassis No	KNAFZ411MH5676707
SINGAPORE 079120	Engine No	G4FGGH653885
Contact No 64191000	Make/Model	KIA/FORTE K3 1.6 A SX HADQ
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	09/07/2021/ 09:07	BLE	261 / Edwin Caina	35774			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	HINGE ASSY-HOOD,RH	BT	1	BR	1.00	34.00	20.00	27.20
M	CARRIER ASSY-FRONT END MODULE				1.00	675.00	20.00	540.00
M	COVER-FR BUMPER	00			1.00	633.00	20.00	506.40
M	CAP-FRONT HOOK	X	nn		1.00	9.00	20.00	7.20
M	MOULDING-FRT BPR LICENSE PLATE	X	nn		1.00	18.00	20.00	14.40
M	LIP ASSY-FRONT BUMPER	X	nn		1.00	55.00	20.00	44.00
M	GRILLE ASSY-RADIATOR	BR		CRU	1.00	328.00	20.00	262.40
M	GARNISH-RADIATOR GRILLE,UPR				1.00	54.00	20.00	43.20
M	STRIP ASSY-FR BUMPER UPR	CAT	X	nn	1.00	29.00	20.00	23.20
M	MOULDING-FRONT BUMPER A/INTAKE	X	nn		1.00	91.00	20.00	72.80
M	ABSORBER-FRONT BUMPER ENERGY	X	nn		1.00	84.00	20.00	67.20
M	STIFFNER-FR BPR LWR	X	nn		1.00	114.00	20.00	91.20
M	RAIL ASSY-FR BUMPER	X	nn	X	1.00	496.00	20.00	396.80
M	BRACKET-FR BUMPER SIDE MTG,LH	X	nn	X	1.00	13.00	20.00	10.40
M	BRACKET-FR BUMPER SIDE MTG,RH	X	nn	X	1.00	13.00	20.00	10.40
M	WIRING HARNESS-FR BUMPER	X	nn		1.00	237.00	20.00	189.60
M	ULTRASONIC SENSOR ASSY-P.A.S	X	nn		4.00	177.00	20.00	566.40
M	ORNAMENT-KIA NO.115	REC			1.00	32.00	20.00	25.60
M	GLASS-WINDSHIELD	BR			1.00	956.00	20.00	764.80
M	MOULDING-WINDSHIELD GLASS			REC	1.00	62.00	20.00	49.60
M	BRACKET, IU ADHESIVE	REC			1.00	26.00	00.00	26.00
M	CONDENSER ASSY-COOLER	?	X	nn	1.00	681.00	20.00	544.80
M	RADIATOR ASSY	X	nn		1.00	546.00	20.00	436.80
M	BLOWER ASSY	X	nn		1.00	623.00	20.00	498.40
M	LATCH ASSY-HOOD	X	nn		1.00	65.00	20.00	52.00
M	PAD-HOOD INSULATING	X	nn		1.00	141.00	20.00	112.80
M	CLIP-HOOD INSULATING PAD MTG	X	nn		11.00	1.00	20.00	8.80
M	COOLANT (4L)	X	nn		1.00	26.00	23.00	20.02

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: 9/7/21, 11:30am

DATE: 09-14-21

REMARKS: EXHIBIT - ?

SURVEYOR NAME: Steve CLKK  
 SURVEYOR SIGNATURE: 9/7/21, 11-30am  
 DATE: 09-11-21  
 REMARKS: EXTRA - ?

**Confirm & accepted by**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

P/P, My Bel Sy  
7 & dys

Nett 14,928.02  
 7% GST on 14928.02 1044.96  
**Total Payable 15,972.98**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.