



Your Ref: S1M035DA

Date: 05th Aug 2021

Our Ref: CS3/ASM21003344/Evf3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Chong Arnold

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJP 5619E

INSURED VEHICLE: SMX 3344H

ACCIDENT DATE: 12/03/2021

We thank you for your instruction on 08/07/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJP 5619E from M/s Oh Appraisal Services.
- b) Singapore Accident Statement of Vehicles SJP 5619E and SMX 3344H
- c) Police Report of Vehicles SJP 5619E.
- d) Final Repair Bill of SJP 5619E from M/s Hiap Lek Automobile Trading.
- e) Colour damaged vehicle photographs of SJP 5619E.

Pre-Repair Inspection Date : 15/03/2021 at M/s 160 Sin Ming Drive #05-07, Repairer: Hiap Lek Automobile Trading.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJP 5619E
Make & Model	: Hyundai Avante (HD) 1.6 DOHC AT ABS Airbag 2WD
Year of Registration	: 2009
Chassis Number	: KMHDU41BR9U720561
Engine Capacity	: 1591 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.