

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chnmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
GA EXPRESS

Singapore

Claimant Insurer: China Taiping Insurance (Singapore) Pte. Ltd.**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA (GBJ3595D)
Policy No:	DMCVSNW00039712100	Date of Loss:	06/07/2021
Vehicle Reg. No.:	YN2245C	Driveable?	
Party At Fault:	UNKNOWN	Driver (Insured):	NADIRAH D/O ANWAR BASAH
Driver (TP):	HTUN HTUN AYE	Vehicle Reg. Date:	26/04/2011
Make/Model:	ISUZU FRR90SUQA-C, 5.2 D (M)	Chassis No:	JALFRR907B7000031
Vehicle Colour:	WHITE		
Engine No:	YD25046253B		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REER TO GIA REPORT ATTACHED.		
Remarks:	VEHICLE CURRENTLY LYING AT WOODLANDS WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

COST OF CLAIMS		Amount
Parts		5,201.00
Miscellaneous Items		0.00
Labour		3,490.00
Paintwork Labour		0.00
Towing		0.00
Gross Total (\$)		8,691.00
+ GST 7.00% (\$)		608.37
Nett Amount (\$)		9,299.37

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

YN2245C

TP/china

Reference

Part Source: (Last Synchronised: 22 Jul 2021)
Parts: N/A ISUZU FRR90SUQA-C 5.2 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for YN2245C)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER	By	0.00	0.00 *680.00F
2	1		*1 PC FRT BUMPER LH BRACKET	0.1	0.00	0.00 *41.00F
3	1		*1 PC FRT BUMPER STEP RUBBERS @22/PC	Na	0.00	0.00 *44.00F
4	1		*1 PC FRT LH STEP TRAY	By	0.00	0.00 *128.00F
5	1		*1 PC FRT LH STEP TRAY BRACKET	7	0.00	0.00 *175.00F
6	1		*1 PC FRT LH STEP TRAY SIDE GARNISH	CM	0.00	0.00 *128.00F
7	1		*4 PCS FRT LH STEP TRAY SIDE GARNISH CLIPS @3/PC	Na	0.00	0.00 *12.00F
8	1		*4 PCS FRT LH STEP TRAY LAMP	MSD	0.00	0.00 *25.00F
9	1		*4 PCS FRT LH STEP TRAY MUD FLAP	CM	0.00	0.00 *18.00F
10	1		*1 PC AIR-CON CONDENSER	RT/Pu	0.00	0.00 *850.00F
11	1		*1 PC AIR-CON GAS PIPE	By	0.00	0.00 *115.00F
12	1		*1 PC FRT LH DOOR	By	0.00	0.00 *980.00F
13	1		*1 PC FRT LH DOOR LOWER OUTER GARNISH	CM	0.00	0.00 *220.00F
14	1		*1 PC FRT LH DOOR BOTTOM HINGE	By	0.00	0.00 *69.00F
15	1		*1 PC FRT LH DOOR LAMP	Na	0.00	0.00 *45.00F
16	1		*1 PC FRT LH SIDE MIRROR SQUARE	Del / By	0.00	0.00 *116.00F
17	1		*1 PC FRT LH SIDE MIRROR ROUND	By	0.00	0.00 *69.00F
18	1		*1 PC FRT LH SIDE MIRROR STAY	By	0.00	0.00 *205.00F
19	1		*1 PC FRT LH CORNAL SIDE GARNISH	By	0.00	0.00 *170.00F
20	1		*1 PC LH SIDE LAMP	CM	0.00	0.00 *72.00F
21	1		*1 PC LH HEADLAMP	CM	0.00	0.00 *224.00F
22	1		*1 PC FRT LH WHEEL ARP GARNISH	CM	0.00	0.00 *149.00F
23	1		*1 PC FRT LH WHEEL FRT MUDFLAP	CM	0.00	0.00 *130.00F
24	1		*1 PC FRT GRILLE	By	0.00	0.00 *428.00F
25	1		*1 PC FRT LIP EMBLEM (ISUZU)	Na	0.00	0.00 *108.00F

F=Franchise part.

Total Parts (\$)

5,201.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

<https://singapore.merimen.com/claims/index.cfm?fuseaction=MTRrepairer&fuseaction=...> 22/07/2021

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE & REFIX FRT LH DOOR, TRANSFER ATTACHMENT, LH SIDE LAMP & HEADLAMP, SIDE MIRROR, STEP TRAY, WHEEL ARP GARNISH, TO KNOCK OUT, STRAIGHTEN FRT LH W/SCREEN PILLAR, FRT LH FLOOR BOARD PANEL & REALIGN THE SAME	New	1,100.00 <i>850</i>
2	REMOVE & REFIX FRT LH DOOR GLASS, CHECK CENTRE LOCKING & POWER MIRROR	New	60.00 ✓
3	REMOVE & REFIX AIRCON, CHECK, VACUUM & REFILL GAS	New	100.00 ✓
4	PUTTY & RESPRAY ON FRT BUMPER, FRT LH W/SCREEN PILLAR, FRT LH CORNAL GARNISH, FRT LH DOOR	New	800.00 <i>700</i>
5	TO REWRITE SIGNAL LAMP WIRE HARNESS AND CHECK WIRING	New	50.00 <i>201</i>
6	TO SUPPLY 1 PC REAR TRUCK WOODEN CROSS MEMBER, LABOUR TO REMOVE & REPLACE WOODEN CROSS MEMBER INCLUDING SUPPLY ALL NECESSARY MATERIAL & LIFT UP REAR WOODEN TRUCK	New	1,000.00 <i>750</i>
7	TO REWRITE ADVERTISEMENT <i>(Bill)</i>	New	380.00 <i>300</i>
Gross Labour Cost (S\$)			3,490.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >