

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chee So Chow

Date: 23 Jul 2021

## **Preliminary Advice**

Insured	: GBJ3595D		
Vehicle No			
TP Vehicle	: YN2245C	Accident Date	: 06/07/2021
No			
Make	: ISUZU FRR90SUQA-C	Assignment Date	: 15/07/2021
Date of	: 22/07/2021	Est. Duration of	: 9
Inspection		Repair	
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN)		
	BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A		
	SINGAPORE 768761		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,691.00
Revised Amount	:S\$	6,786.00
Check Items (Estimated)	:S\$	1,206.00
Total	:S\$	7,992.00

Lump Sum Repair	:S\$
-----------------	------

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :