

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21007484/VVF3Q2
Date: 16/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070146203
Claimant Vehicle No :	SJC6430T	Insured Vehicle No :	SNA120R
Date of Loss:	06/07/2021	Nature of Claim:	TP
		Claim No:	4544078535SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC6430T	Engine No:	G4FC7U244360
Make & Model:	HONDA ACCORD, 1.6 (M)	Chassis No:	KMH DU41BR7U287698
Reg. Date:	26/02/2008 (Man. Year: 2007)	Odometer:	1185180 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 4 mm	Rear Left Side:	West Lake 4 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

7/16/2021

Adjuster Report

Date of Assignment: 09/07/2021

Date Inspected: 09/07/2021 Inspected At:

Hock Motors Workshop (HQ)
NO 1 KAKI BUKIT AVENUE 6, #02-38 AUTOBAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/16/2021

Adjuster Report

MARKET VALUE:\$35,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Bent	0.00 F	*- F
3	1		*REAR BUMPER	Dented	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Broken	0.00 F	*- F
5	1		*REAR BUMPER BRACKET	Broken	0.00 F	*- F
6	1		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
7	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
8	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
9	1		*REVERSE SENSOR	Cut	0.00 F	*- F
10	1		*REAR END PANEL	Burst	0.00 F	*- F
11	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
12	1		*REAR LH TAILLAMP PANEL	Distorted	0.00 F	*- F
13	1		*REAR RH TAILLAMP	Cut	0.00 F	*- F
14	1		*BOOTLID	Dented	0.00 F	*- F
15	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
16	1		*BOOTLID HANDLE	Necessary	0.00 F	*- F
17	1		*BOOTLID MOULDING	Necessary	0.00 F	*- F
18	1		*BOOTLID LAMP LH	Cracked	0.00 F	*- F
19	1		*BOOTLID LOCK	Distorted	0.00 F	*- F
20	1		*BOOTLID RUBBER	Cut	0.00 F	*- F
21	1		*BOOTLID INNER TRIM	Torn	0.00 F	*- F
22	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >