



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 5271L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED / DENTED	955.70	683.40
2	REAR BUMPER SIDE RETAINER @\$65.20	SERVICEABLE	130.40	-
1	REAR TOW COVER	SERVICEABLE	25.70	-
	LESS 20% DISCOUNT		-222.36	-136.68
			889.44	546.72
SPECIAL NETT ITEMS				
4	REAR REVERSE SENSOR (SN)	SHORTED / SCRATCHED	300.00	200.00
10	REAR BUMPER CLIP @\$2.00 (SN)	NECESSARY	20.00	20.00
			320.00	220.00
LABOUR				
	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING.		400.00	200.00
	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION.		600.00	350.00
	CHECK/RECONNECT WIRING.	NOT NECESSARY	40.00	-
	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION.	NOT NECESSARY	100.00	-
			1,140.00	550.00
GRAND TOTAL			2,349.44	1,316.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,050.00

Report Ref No. CS/AGI21007487/Kuf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.