

ASS. REC. BY:

REF: CS/

AG2 / 210074871Kof3

C

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJD 5271L

at Workshop m/s Massive

of \_\_\_\_\_

Insured: SLQ 5494T

Policy No. \_\_\_\_\_

Claims No. C10010791/KY

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 03/03 Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SJD 5271L Yr Regn: 03, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MPV

Make: Honda Proton c.c. 1799

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 157527 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHM RN 68408S 202342

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil S/Rim / STD A/Rim or

Tyre Size: F: 225/45 ER17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 7/1/21 D.O.I. 13/7/2021

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	Est not ready
22/7	LI Pump @ 10500 Costumed 2 repair days. (RED \$1521.80; 59%)

Date/Time, File Pass to?

: Prell. Report

1) 23/8 TYPIST

: Final Report

Date/Time, File Return to?

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation: \_\_\_\_\_ \$ + RS. \_\_\_\_\_ SI

Fuel:

Others:

TOTAL

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Report Format: TP

Lump Sum / LB: (\$ \$1050)

# Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial PK 2 Singapore 569541  
H/P 91082728

Fax : 64816131

Raj Kumar S/O Kalamani  
216A Boon Lay Ave  
#04-225  
Singapore 641216

*Not authorized*  
*LLP @ 1050/h*  
*Resurvey After Painting*  
*2 days*

Vehicle No : SJD 5271 L  
Make : Honda Stream  
Year : 2008

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

### Estimate Cost Of Repair

1 pc	Rear bumper	<i>683.40</i>	<i>Buclaw</i> \$955.70 ✓
2 pcs	Rear bumper side retainer		\$65.20 <i>sm</i> \$130.40 X
1 pc	Rear tow cover		<i>sm</i> \$25.70 X
			\$1,111.80
Less 20 %			\$222.36
			\$889.44

### S. Nett Item

4 pcs	Rear reverse sensor		<i>phon / sen</i> \$300.00 <i>200sm</i>
10 pcs	Rear bumper clip		\$2.00 <i>sm</i> \$20.00 ✓
			\$320.00

### Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$400.00	<i>200l</i>
To putty & spray paint on accident affected portion.	\$600.00	<i>350l</i>
Check/reconnect wiring.	\$40.00	<i>nn</i> X
To spray anti rust on accident affected portion.	\$100.00	<i>nn</i> X
<b>Total</b>	<b>\$2,571.80</b>	

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before *after* spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: