



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 2554Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	DOOR PANEL FRT LH V5 (SN)	BENT	9,890.70	9,890.70
1	SEAL-DOOR (SN)	NECESSARY	929.50	929.50
1	SOUND DEADENING PAD (SN)	NECESSARY	578.00	578.00
15	BUMPER NUT XF (SN)	NECESSARY	67.50	67.50
			11,465.70	11,465.70
LABOUR				
TO REPLACE FRT LH DOOR, REPAIR REAR LH DOOR, LH REAR FENDER, REAR BUMPER, ETC.			5,000.00	3,250.00
TO SPRAYPAINT ON FRT LH DOOR, REAR LH DOOR, REAR LH FENDER, REAR BUMPER, ETC.			4,500.00	4,000.00
TO REMOVE, REFIT & TRANSFER FRT LH DOOR PARTS.			500.00	500.00
TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.			621.00	621.00
			10,621.00	8,371.00
GRAND TOTAL			22,086.70	19,836.70
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				19,836.70

Report Ref No. CS/CWF21007494/Rtf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.