


ASS. REC. BY: Steve CS/AIG 2100 7497 ETP3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
QD/TP/WS/TP RES/OD RES/EVA/INV/INV
To inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
DIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Cum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGC5892X Yr Regn: 6/11/29
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: KIA Cervo c.c. 1591
Colour: Slv A/O: Insured / Std / NI / N
Sp. Reading: 34837 T/Radio: Insured / Std / NI / N
Eng/No: _____
C/No: KM11F5416MK:5052314
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Locked / Burnt or
Brake: Inorder / Jammed / Locked / Burnt or
Modl: NII / S/Rim / STD A/Rim or
Tyre Size: F: 225/45R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or B Kumho
Front Rear
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 8/7/21 O.O.I. 9/7/21
Survey held at Cycle & Carriage
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>MR-88K</u>

File/Time, File, Post to? ☐ : Prel. Report
☐ : Final Report

File/Time, File Return to?

Approved: _____
Date: _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Inve (\$ _____)
☐ : Wash and (\$ _____)

Survey Fee:	
Transportation	
8 + RS	
Police	
Others	
TOTAL	



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
JACKSON LIM JEK SHENG (LIN YICHENG)	Cust No/Name /JACKSON LIM JEK SHENG (LIN YICH
BLK 275D JURONG WEST STREET 25	Reg No/Reg Date SGC5802X / 06/01/202
#13-67	Date In/Mileage / 0
SINGAPORE 644275	Chassis No KNAF5416MK5052314
Contact No Mobile: 6583630363	Engine No G4FGKH749375
	Make/Model KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	09/07/2021/ 11:56	BLC	442 / CocoLu	35809			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1200 1750.00
RENEW FRT BUMPER, FRT SUPPORT PANEL, BONNET REPAIR FRT FENDER RH & LH					3 X 400			
E PNT98000								1400 1750.00
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH					4 X 350			
E PNT88000								100.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								
M SUNDRY								50.00
FRT NUMBER PLATE WITH FRAME								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
E PNT88000								100.00
REMOVE & INSTALL PARKING SENSOR								
M SUNDRY								80.00
TOP UP AIRCON GAS								
M SUNDRY								40.00
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								20.00
Sundry								
M COVER-FR BUMPER					1.00	633.00	00.00	633.00
M GRILLE-FRONT BUMPER					1.00	485.00	00.00	485.00
M GRILLE ASSY-RADIATOR					1.00	328.00	00.00	328.00
M GARNISH-RADIATOR GRILLE					1.00	38.00	00.00	38.00
M LAMP ASSY-FRONT FOG,RH					1.00	303.00	00.00	303.00
M LAMP ASSY-FRONT FOG,LH					1.00	303.00	00.00	303.00
M MOULDING-FRONT BUMPER,RH					1.00	216.00	00.00	216.00
M MOULDING-FRONT BUMPER,LH					1.00	216.00	00.00	216.00
M LAMP ASSY-SIDE REPEATER,RH					1.00	143.00	00.00	143.00
M LAMP ASSY-SIDE REPEATER,LH					1.00	143.00	00.00	143.00
M ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	00.00	84.00
M STIFFNER-FR BPR LWR					1.00	114.00	00.00	114.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
JACKSON LIM JEK SHENG (LIN YICHENG)	Cust No/Name /JACKSON LIM JEK SHENG (LIN YICH
BLK 275D JURONG WEST STREET 25	Reg No/Reg Date SGC5802X / 06/01/202
#13-67	Date In/Mileage / 0
SINGAPORE 644275	Chassis No KNAF5416MK5052314
Contact No Mobile: 6583630363	Engine No G4FGKH749375
	Make/Model KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	09/07/2021/ 11:56	BLC	442 / CocoLu	35809			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	ULTRASONIC SENSOR ASSY-P.A.S	X			1.00	163.00	00.00	163.00
M	BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	00.00	22.00
M	BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	00.00	22.00
M	PANEL ASSY-HOOD	X			1.00	1502.00	00.00	1502.00
M	BEAM COMPLETE-FR BUMPER				1.00	497.00	00.00	497.00
M	CARRIER ASSY-FRONT END MODULE				1.00	675.00	00.00	675.00
M	PAD-HOOD INSULATING	X			1.00	156.00	00.00	156.00
M	LATCH ASSY-HOOD				1.00	103.00	00.00	103.00
M	ORNAMENT-KIA NO.115				1.00	32.00	00.00	32.00
M	LAMP ASSY-HEAD,RH				1.00	2210.00	00.00	2210.00
M	LAMP ASSY-HEAD,LH				1.00	2210.00	00.00	2210.00
M	TUBE ASSY-SUCTION & LIQUID				1.00	462.00	00.00	462.00
M	HOSE-DISCHARGE				1.00	122.00	00.00	122.00
M	GUARD-AIR,RH				1.00	28.00	00.00	28.00
M	GUARD-AIR,LH				1.00	28.00	00.00	28.00
M	CONDENSER ASSY-COOLER				1.00	687.00	00.00	687.00
P	BRACKET ASSY-RADIATOR MTG,UPR				2.00	29.00	00.00	58.00
M	RADIATOR ASSY				1.00	646.00	00.00	646.00
P	INSULATOR-RADIATOR MTG,LWR				2.00	9.00	00.00	18.00
M	BLOWER ASSY				1.00	656.00	00.00	656.00

Estimate

Steve CLKK)
 9/7/21, 12:00pm

90-N1 AL
 EXACT -?

P/P. M B/L Sg
 7 dys

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

Confirm & accepted by illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

Nett	17,343.00
7% GST on	1214.01
Total Payable	18,557.01

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.