

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21007501/KRA3Q2
Date: 19/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070056805
Claimant Vehicle No :	SMP1261T	Insured Vehicle No :	SMT1381J
Date of Loss:	03/07/2021	Nature of Claim:	TP
		Claim No:	5049350050SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP1261T		
Make & Model:	LEXUS ES250, 2.5 (A)	Engine No:	2ARF221181
Reg. Date:	15/07/2016 (Man. Year: 2016)	Chassis No:	JTHBJ1GGX02093045
Colour:	Metallic Pearl White	Odometer:	73006 km
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,787.55	4,716.90	70.65	1.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	1,340.00	300.00	18.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,427.55	6,056.90	370.65	5.77
Approved Total (Overridden) (S\$)		4,800.00		

(S\$)	6,427.55	4,800.00	1,627.55	25.32
+ GST 7.00/7.00% (S\$)	449.93	336.00	113.93	25.32
Nett Amount (S\$)	6,877.48	5,136.00	1,741.48	25.32
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 08/07/2021

Date Inspected: 08/07/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent	1,413.60 FL	*1,413.60 FL
2	1		*FRONT RH DOOR GLASS	Shattered	1,110.90 FL	*1,110.90 FL
3	1		*FRONT RH DOOR GLASS OUTER MOULDING	Dented	172.70 FL	*172.70 FL
4	1		*FRONT RH DOOR GLASS REGULATOR	Distorted	218.50 FL	*218.50 FL
5	1		*FRONT RH DOOR GLASS CHANNEL	Dented	170.80 FL	*170.80 FL
6	1		*FRONT RH DOOR INNER RUBBER (50%)	Dented / Cut	211.95 FS	*141.30 FS
7	1		*FRONT RH DOOR TOP HINGE	Bent	97.50 FL	*97.50 FL
8	1		*SET FRONT RH DOOR FRAME STICKER	Missing	128.60 FL	*128.60 FL
9	1		*FRONT RH SIDE MIRROR	Mtg Distorted	2,788.20 FL	*2,788.20 FL
					Sub Total (\$\$)	6,312.75
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,525.20
					Total Parts (\$\$)	4,787.55

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT RH DOOR ,TRANSFER LOCK ASSY ,INNER BOARD ,RUBBER ,SIDE MIRROR ,KNOCK & REPAIR FRT RH FENDER ,FRT RH W/SCREEN PILLAR & REALIGN THE SAME	New	600.00	500.00
2	PUTTY & RESPRAY ON FRT RH W/SCREEN PILLAR ,FRT RH FENDER ,FRT RH DOOR ,SIDE MIRROR & ALL AFFECTED AREAS (PEARL WHITE)	New	900.00	700.00
3	REMOVE & REFIX FRT RH DOOR GLASS	New	60.00	60.00
4	TO RESET LOCK SYSTEM AND SIDE MIRROR	New	50.00	50.00
5	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (S\$)			1,640.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >