

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21007504/ABA3Q2
Date: 12/10/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0001912_01
Claimant Vehicle No :	SGD1328U	Insured Vehicle No :	SGY8536D
Date of Loss:	03/07/2021	Nature of Claim:	TP
		Claim No:	MPC2021D0002932

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGD1328U	Engine No:	2AZF319550
Make & Model:	TOYOTA ESTIMA, 2.4 Aeras G (A)	Chassis No:	ACR500102369
Reg. Date:	08/01/2010 (Man. Year: 2009)	Odometer:	81546 km
Colour:	Black		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,027.67	766.92	260.75	25.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	550.00	350.00	38.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,927.67	1,316.92	610.75	31.68
Approved Total (Overridden) (S\$)		1,050.00		

	(S\$)	1,927.67	1,050.00	877.67	45.53
+ GST 7.00/7.00% (S\$)		134.94	73.50	61.44	45.53
Nett Amount (S\$)		2,062.61	1,123.50	939.11	45.53
+ Loss of Use (3.0 x S\$100.00/day) (S\$)			300.00		
			1,423.50		
			1,400.00		

INSPECTION

Date of Assignment: 09/07/2021

Date Inspected: 02/08/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2021)
Parts: M1-MPV	TOYOTA ESTIMA 2.4 Aeras G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGD1328U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	715.90 FL	*715.90 FL
2	2		*REAR BUMPER SIDE HOLDER-LH & RH	Not Necessary	125.00 FL	*- FL
3	1		*REAR BUMPER REFLECTOR -RH	Not Necessary	67.10 FL	*- FL
4	1		*REAR BUMPER LOWER COVER	Not Necessary	48.90 FL	*- FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
6	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,266.90	945.90
- List Item Discount on L Items 25.00/25.00% (S\$)	239.23	178.98
Total Parts (S\$)	1,027.67	766.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	400.00	250.00
2	TO PUTTY & SPRAY UP PAINT WORKS (FRONT)	New	400.00	250.00
3	TO REMOVE REVERSE SENSOR	New	100.00	50.00
			Gross Labour Cost (\$\$)	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >