

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21007506/AGUF3E2**Date:** 13/12/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80484650QMX
Claimant Vehicle No :	SLC2931S	Insured Vehicle No :	SKS1374J
Date of Loss:	07/07/2021	Nature of Claim:	TP
		Claim No:	636954

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC2931S		
Make & Model:	HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A)	Engine No:	L15B4030225
Reg. Date:	09/05/2016 (Man. Year: 2015)	Chassis No:	RU11110221
Colour:	Black	Odometer:	181547 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,558.08	7,397.04	4,161.04	36.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,620.00	2,610.00	1,010.00	27.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,178.08	10,007.04	5,171.04	34.07
Approved Total (Overridden) (\$\$)		7,500.00		
Nett Amount (\$\$)	15,178.08	7,500.00	7,678.08	50.59

INSPECTION

Date of Assignment:	09/07/2021	Sin Yu Sin Workshop (HQ)
Date Inspected:	12/07/2021 Inspected At:	1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit)
Estimated Period of Repair:	9.0 days	Singapore 417883

Adjuster: XING GUO QIANG**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2021)

Parts: 144 HONDA VEZEL 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLC2931S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Distorted	1,287.10 FL	*1,100.00 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	104.10 FL	*104.10 FL
3	1		*REAR TAILGATE LOGO EMBLEM	Not Necessary	69.10 FL	*- FL
4	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	68.50 FL	*68.50 FL
5	2		*REAR TAILGATE REFLECTOR LAMP L/R	Cracked	641.60 FL	*641.60 FL
6	1		*REAR TAILGATE WEATHER STRIP	Cut	198.70 FL	*198.70 FL
7	1		*REAR TAILGATE MECHANISM LOCK	Damaged	256.10 FL	*256.10 FL
8	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	55.00 FL	*- FL
9	1		*REAR TAILGATE INNER TRIM	Cracked	586.50 FL	*285.00 FL
10	1		*REAR TAILGATE INNER HANDLE	Not Necessary	55.20 FL	*- FL
11	1		*REAR TAILGATE SMART KEYLESS SENSOR	Cracked	230.80 FL	*85.00 FL
12	1		*REAR TAILLAMP L/R	N/S Cracked	1,036.40 FL	*441.00 FL
13	1		*REAR BUMPER	Distorted	877.50 FL	*877.50 FL
14	1		*REAR BUMPER INNER BUZZER	Cracked	138.00 FL	*88.00 FL
15	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	137.60 FL	*64.00 FL
16	2		*REAR BUMPER SIDE REFLECTOR L/R	Cracked	185.20 FL	*185.20 FL
17	2		*REAR BUMPER SIDE GARNISH L/R	Deformed	370.40 FL	*370.40 FL
18	1		*REAR END PANEL	Distorted	759.10 FL	*575.00 FL
19	1		*REAR END PANEL GARNISH	Deformed	248.90 FL	*178.00 FL
20	1		*REAR END HOOK PANEL	Repair	342.40 FL	*- FL
21	1		*REAR SPARE TYRE PANEL	Distorted	1,230.00 FL	*1,230.00 FL
22	1		*REAR SPARE TYRE PANEL TOP SPONGE	Cracked	256.30 FL	*256.30 FL
23	1		*REAR SPARE TYRE PANEL TOP BOARD	Deformed	286.50 FL	*286.50 FL
24	1		*REAR SPARE TYRE PANEL UNDER COVER	Deformed	248.80 FL	*248.80 FL
25	2		*REAR FENDER INNER TRIM L/R	Cracked	1,563.20 FL	*650.00 FL
26	1		*REAR FENDER ARCH GARNISH L/R	N/S Cracked	317.20 FL	*158.60 FL
27	1		*REAR EXHAUST SILENCER BOX	Not Necessary	855.00 FL	*- FL
28	3		*REAR EXHAUST SILENCER BOX MOUNTING	Not Necessary	77.40 FL	*- FL
29	1		*REAR EXHAUST SILENCER HEAT SHIELD	Crumpled	165.00 FL	*98.00 FL
30	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
31	1		*REAR REVERSE CAMERA	Not Necessary	400.00 FS	*- FS
32	1		*REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
33	1		*REAR BUMPER GUARD (ASSY)	Missing	280.00 FS	*200.00 FS
34	1		*REAR TAILGATE TRIM BOARD CLIP	Necessary	30.00 FS	*30.00 FS
35	1		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
36	1		*REAR END PANEL GARNISH CLIP	Necessary	20.00 FS	*10.00 FS
37	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
38	2		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*60.00 FS
39	1		*REAR EXHAUST CHROME TIP	Not Necessary	160.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,087.60	9,086.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,529.52	1,689.26
Total Parts (\$\$)	11,558.08	7,397.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO REMOVE AND REINSTALL REAR WINDSCREEN FOR NECESSARY REPAIR	New	150.00	120.00
3	TO TRANSFER BOOT COMPONENT PARTS TO NEW BOOT	New	120.00	80.00
4	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSOR	New	120.00	50.00
5	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE CAMERA	New	80.00	50.00
6	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISH, SEAT, ETC FOR NECESSARY REPAIRS	New	150.00	80.00
7	TO REMOVE, REPLACE AND REINSTALL REAR EXHAUST SILENCER BOX	New	120.00	0.00
8	TO STRAIGHTEN, REPAIR, REALIGN ON FRONT & REAR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,400.00	1,100.00
9	TO SPRAY PAINTING ON AFFECTED AREA	New	1,400.00	1,100.00
Gross Labour Cost (S\$)			3,620.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >