

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007510/RGA3Q2**Date:** 17/03/2022**REFERENCE**

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 1800089003 |
| Claimant Vehicle No : | YP2902D | Insured Vehicle No : | SMC9617S |
| Date of Loss: | 06/07/2021 | Nature of Claim: | TP |
| | | Claim No: | 4863302754SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---|-------------|--------------|
| Reg No: | YP2902D | | |
| Make & Model: | MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M) | Engine No: | 4P10C21819 |
| Reg. Date: | 27/05/2016 (Man. Year: 2016) | Chassis No: | FEB21EA20596 |
| Colour: | Blue | Odometer: | 185624 km |
| Engine Capacity: | 2998 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|-----------------|
| Front Tyre Size: | 195/85 R15 | Rear Tyre Size: | 195/85 R15 (D) |
| Front Left Side: | Yokohama 7 mm | Rear Left Side: | Yokohama 7/7 mm |
| Front Right Side: | Yokohama 7 mm | Rear Right Side: | Yokohama 7/7 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 3,600.00 | 1,300.00 | 2,300.00 | 63.89 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,400.00 | 700.00 | 700.00 | 50.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,000.00 | 2,000.00 | 3,000.00 | 60.00 |
| Approved Total (Overridden) (S\$) | | 1,600.00 | | |
| Nett Amount (S\$) | 5,000.00 | 1,600.00 | 3,400.00 | 68.00 |
| + Loss of Use (4.0 x S\$110.00/day) (S\$) | | 440.00 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| Nett Liability (S\$) | | 2,047.45 | | |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 09/07/2021 | |
| Date Inspected: | 19/07/2021 Inspected At: | YISHUN INDUSTRIAL PARK A, #01-240, YISHUN INDUSTRIAL PARK A, Repairer: Kent Seng Car Services (yishun) (HQ) |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|------------------------------|-----|----------|--|-----------|-------------|-------------------|
| 1 | 1 | | *RIGHT SIDE SLIDING DOOR PANEL (FRONT SIDE) | Torn | 2,500.00 FS | *1,000.00 FS |
| 2 | 1 | | *LETTERING LOGO DRAQING & ADVERTISEMENT ON RIGHT SIDE SLIDING DOOR PANEL | Necessary | 1,100.00 FS | *300.00 FS |
| F=Franchise part. S=SpcNett. | | | | | | |
| Total Parts (S\$) | | | | | | 3,600.00 1,300.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | LABOUR FOR JACKING KNOCKING RIGHT SIDE SLIDING DOOR LOWER BAR ,DISMANTLE & REPLACE RIGHT SIDE SLIDING DOOR PANEL (FRONT SIDE) | New | 600.00 | 300.00 |
| 2 | TO RESPRAY RIGHT SIDE SLIDING DOOR PANEL | New | 800.00 | 400.00 |
| Gross Labour Cost (\$\$) | | | 1,400.00 | 700.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >