

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21007516/ARA3Q2
Date: 19/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070125591
Claimant Vehicle No :	SLB7888G	Insured Vehicle No :	GBF3150A
Date of Loss:	07/07/2021	Nature of Claim:	TP
		Claim No:	9283780223SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB7888G		
Make & Model:	HYUNDAI TUCSON, 1.6 TL GLS (A)	Engine No:	G4FJLH800024
Reg. Date:	14/07/2020 (Man. Year: 2020)	Chassis No:	KMHJ3812VLU285566
Colour:	Grey	Odometer:	9873 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,391.80	9,067.36	10,324.44	53.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	2,250.00	1,330.00	37.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,971.80	11,317.36	11,654.44	50.73
Approved Total (Overridden) (S\$)		9,000.00		

Nett Amount (S\$)	22,971.80	9,000.00	13,971.80	60.82
+ Loss of Use (9.0 x S\$80.00/day) (S\$)		720.00		
Nett Liability (S\$)		9,720.00		

INSPECTION

Date of Assignment: 08/07/2021

Date Inspected: 08/07/2021

Estimated Period of Repair: 7.0 days

Inspected At:

ADVANCE AUTO GARAGE (#03-01) (HQ)
 10 Kaki Bukit Road 2 #03-01, First East Centre,
 Singapore 417868

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Deformed	30.00 FS	*30.00 FS
2	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
3	2		*REAR NUMBER PLATE LAMP	Not Necessary	64.00 F	*- FL
4	1		*REAR BUMPER	Deformed	523.50 F	*523.50 FL
5	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
6	2		*REAR BUMPER SIDE HOLDER	Necessary	97.60 F	*97.60 FL
7	1		*REAR BUMPER TOW COVER	Deformed	38.00 F	*38.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Cracked	389.70 F	*389.70 FL
9	2		*REAR BUMPER REFLECTOR	Cut	131.80 F	*131.80 FL
10	1		*REAR BUMPER LOWER GARNISH	Deformed	358.50 F	*358.50 FL
11	1		*REAR END PANEL	Dented	779.50 F	*779.50 FL
12	1		*REAR END PANEL TOP GARNISH	Deformed	225.90 F	*225.90 FL
13	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
14	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
15	1		*REAR END PANEL ANTENNA SENSOR	Cracked	265.70 F	*265.70 FL
16	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	800.00 F	*400.00 FL
17	1		*TAILLAMP	O/S Cracked	1,790.60 F	*895.30 FL
18	1		*TAILGATE	Distorted	1,698.70 F	*1,698.70 FL
19	1		*TAILGATE LOCK	Damaged	192.40 F	*192.40 FL
20	1		*TAILGATE WEATHERSTRIPE	Cut	186.90 F	*186.90 FL
21	2		*TAILGATE LAMP	Cracked	1,743.00 F	*1,743.00 FL
22	1		*TAILGATE LOWER GARNISH	Cracked	595.70 F	*595.70 FL
23	2		*TAILGATE LOWER GARNISH REFLECTOR	Cut	131.80 F	*131.80 FL
24	1		*TAILGATE LOWER GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
25	1		*TAILGATE CAMERA	Damaged	480.00 FS	*480.00 FS
26	1		*TAILGATE INNER TRIM	Deformed	458.90 F	*458.90 FL
27	1		*TAILGATE INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
28	2		*TAILGATE AUTO DAMPER	Not Necessary	2,018.00 F	*- FL
29	1		*TAILGATE GLASS MOULDING	Necessary	125.10 F	*125.10 FL
30	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
31	1		*HYUNDAI LOGO	Necessary	75.00 F	*75.00 FL
32	1		*TUCSON WORDING	Necessary	68.00 F	*68.00 FL
33	1		*REAR FENDER INNER TRIM BOARD	O/S Cracked	756.80 F	*378.40 FL
34	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
35	1		*REAR FENDER INNER SHIELD	O/S Torn	296.00 F	*148.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR FENDER INNER SHIELD CLIPS	Necessary	40.00 FS	*20.00 FS
37	1		*FLOOR PANEL TOP BOARD	Deformed	401.80 F	*401.80 FL
38	1		*REAR EXHAUST PIPE	Not Necessary	1,282.00 F	*- FL
39	1		*REAR EXHAUST MOUNTING	Not Necessary	45.10 F	*- FL
40	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	151.40 F	*- FL
41	2		*REAR CORNER RADAR UNIT	Not Necessary	2,830.40 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	19,391.80	11,129.20
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	2,061.84
Total Parts (S\$)	19,391.80	9,067.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	900.00
3	WIRING	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	60.00
5	TO SPRAY TUFF COAT	New	150.00	80.00
6	TO REMOVE TAILGATE CAMERA	New	100.00	50.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE REAR VIDEO CAMERA	New	100.00	50.00
10	TO REMOVE UPHOLSTERY	New	150.00	80.00
11	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (S\$)			3,580.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >