

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21007517/ARA3Q2
Date: 11/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210037527
Claimant Vehicle No :	SBN9868G	Insured Vehicle No :	SMZ1693C
Date of Loss:	06/07/2021	Nature of Claim:	TP
		Claim No:	4686206002SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBN9868G	Engine No:	K24Z32352542
Make & Model:	HONDA ACCORD, 2.4 (A)	Chassis No:	JHMCU26409C208703
Reg. Date:	08/05/2009 (Man. Year: 2009)	Odometer:	94145 km
Colour:	Grey		
Engine Capacity:	2354 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,828.30	1,951.28	3,877.02	66.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,160.00	1,640.00	58.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,628.30	3,111.28	5,517.02	63.94
Approved Total (Overridden) (S\$)		2,500.00		

Nett Amount (S\$)	8,628.30	2,500.00	6,128.30	71.03
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,107.45		

INSPECTION

Date of Assignment: 08/07/2021

Date Inspected: 08/07/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Ysk Auto Workshop (HQ)
 No.1 Kaki Bukit Avenue 6, #01-49 Autobay
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,285.00 F	*1,285.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SIDE HOLDER	Necessary	108.20 F	*108.20 FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	245.60 F	*245.60 FL
5	1		*REAR BUMPER REFLECTOR	O/S Cracked	170.00 F	*85.00 FL
6	1		*REVERSE SENSOR	Damaged	350.00 FS	*250.00 FS
7	1		*REAR END PANEL	Repair	558.70 F	*- FL
8	1		*REAR END PANEL TOP GARNISH	Not Necessary	245.90 F	*- FL
9	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
10	1		*BOOTLID	Repair	988.20 F	*- FL
11	1		*HONDA LOGO	Necessary	49.40 F	*49.40 FL
12	1		*ACCORD WORDING	Necessary	68.90 F	*68.90 FL
13	1		*EURO WORDING	Necessary	59.50 F	*59.50 FL
14	1		*REAR EXHAUST PIPE	Repair	1,458.90 F	*- FL
15	1		*REAR EXHAUST CHROME PIPE RH	Bent	150.00 FS	*150.00 FS
					Sub Total (\$\$)	5,828.30
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00
					Total Parts (\$\$)	1,951.28

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	400.00
2	SPRAY PAINTING	New	1,000.00	500.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	30.00
6	TO SPRAY TUFF COAT	New	150.00	30.00
7	TO REMOVE REAR EXHAUST PIPE	New	200.00	120.00
8	TO TRANSFER BOOTLID FITTINGS	New	150.00	0.00
Gross Labour Cost (S\$)			2,800.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >