

TP AIG.

Justin.

SBN 9868G. 2009 May.

Honda Accord. 2354 cc

JHMCU26409C208703

	Reer Bumper	Distorted	1285	✓
	Reer Bumper Clips.	in	30(SN)	✓
	Reer Bumper Side Holder x 02	Reer	$54.1 \times 2 = 108.20$	✓
	Reer Bumper Reinforcement	Dented	245.60	✓
	Reer Bumper Pellerlas x 02	RH Cmld	$85 \times 2 = 170$	85
	Reverse Sensor	Dmgd	350(SN)	250(SN)
1901.60	Reer End Panel.	Regr	558.70	+
1524.28.	Reer End Panel Top Garnish?		245.90	+
S.N. 430	Reer End Panel Sealant.	HP in	60(SN)	-
	Bootlid	Regr	988.20	+
	Honda Logo		49.40	✓
	Accord Wording.	in	68.90	✓
	Euro Wording.		59.50	✓
	Reer Exhaust Pipe.	Regr	1438.90	+
	Reer Exhaust Chrome Pipe RH.	Bent	150(SN)	✓

SBN 98686.

Panel Beating

Spray Painting

Wiring

To remove reverse sensor

To remove upholstery.

To spray tuff coat.

To remove rear exhaust pipe

To transfer bottled fittings.

~~1000~~ 400

~~1000~~ 500

~~50~~ 30

~~100~~ 50

~~150~~ 30

~~150~~ 30

~~200~~ 120

150. X.

1160

Total: 3111.28

L/S: 2.5K.

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: