

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21007520/AQCN2**Date:** 14/10/2021**REFERENCE**

Insured/Claimant: RANJEEV KUMAR NANTA KUMAR Policy No: 1800058563-02
Date of Loss: 05/07/2021 Nature of Claim: OD Claim No: 4882795594SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA377D**
Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZ443895
Reg. Date: 25/05/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V0J1059995
Colour: Blue Odometer: 34291 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,730.00	5,220.16	3,509.84	40.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,172.00	4,602.00	5,570.00	54.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,902.00	9,822.16	9,079.84	48.04
+ GST 7.00/7.00% (S\$)	1,323.14	687.55	635.59	48.04
Nett Amount (S\$)	20,225.14	10,509.71	9,715.43	48.04

INSPECTION

Date of Assignment: 12/07/2021

Date Inspected: 09/07/2021

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Dented	3,039.00 FS	*2,431.20 FS
2	1		*FRONT DOOR OUTER SEAL LH	Necessary	161.00 FS	*128.40 FS
3	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
6	1		*FRONT DOOR ATTACHMENT PARTS LH	Not Necessary	241.00 FS	*- FS
7	1		*FRONT DOOR CATCH LH	Not Necessary	105.00 FS	*- FS
8	1		*FRONT EXTRIOR MOUNTING LH	Not Necessary	1,012.00 FS	*- FS
9	1		*FRONT WING MIRROR CAP LH	Not Necessary	169.00 FS	*- FS
10	1		*REAR DOOR LH	Dented	3,019.00 FS	*2,431.20 FS
11	1		*REAR DOOR OUTER SEAL LH	Necessary	161.00 FS	*128.40 FS
12	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
13	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
14	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
15	1		*REAR DOOR ATTACHMENT PARTS LH	Not Necessary	129.00 FS	*- FS
16	1		*REAR DOOR CATCH LH	Damaged	94.00 FS	*74.80 FS
17	1		*SUNDRIES	Necessary	350.00 FS	*26.16 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	8,730.00 5,220.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID.CHECK FUNCTION	New	280.00	0.00
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	700.00	560.00
3	TO DISMANTLE AND REINSTALL REAR BUMPER.TO RENEW LHS FRONT DOOR AND LHS REAR DOOR.TO REPAIR LHS FRONT FENDER AND LHS SILL PANEL.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,500.00	1,100.00
4	TO RESPRAY REAR BUMPER,LHS REAR FENDER,LHS REAR DOOR,LHS FRONT DOOR,LHS WING MIRROR COVER,DOOR HANDLE,LHS SILL PANEL AND LHS FRONT FENDER	New	5,500.00	2,750.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			10,172.00	4,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >