

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 1092J

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-----------------------------|----------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | • |
| 1 | FRONT BUMPER | DEFORMED / HOLDER TORN | 856.50 | 706.00 |
| 1 | FRONT BUMPER SIDE RETAINER RH | DAMAGED / NECESSARY | 38.50 | 13.00 |
| 1 | FRONT BUMPER FOG LAMP CHROME RING RH | SPILT | 198.45 | 127.00 |
| 1 | FRONT BUMPER CHROME RING LED LIGHT RH | SERVICEABLE | 265.50 | - |
| 1 | BONNET | SERVICEABLE | 896.50 | - |
| 1 | HEADLAMP RH | DEFACED / HOLDER CRACKED | 798.00 | 663.00 |
| 1 | FRONT FENDER RH | TO REPAIR SEE LABOUR | 585.50 | - |
| 1 | FRONT FENDER INNER SHIELD RH | TORN | 121.50 | 98.00 |
| 1 | FRONT BUMPER LOWER GRILLE | SERVICEABLE | 199.40 | - |
| 1 | FRONT RADIATOR GRILLE | SERVICEABLE | 452.80 | - |
| | LESS 10% DISCOUNT | | -441.27 | -160.70 |
| | | | 3,971.38 | 1,446.30 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SET FRONT BUMPER CLIPS (SN) | NECESSARY | 50.00 | 45.00 |
| 1 | FRONT TYRE RIM RH (SN) | SERVICEABLE | 556.00 | - |
| | | | 606.00 | 45.00 |
| | LABOUR | | | |
| | TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH. | | 675.00 | 200.00 |
| | PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL. | | 650.00 | 400.00 |
| | APPLY RUST PROOFING ON THE ADJACENT PANELS. | NOT NECESSARY | 40.00 | - |
| | SPECIALIST CHARGES - WHEEL ALIGNMENT. | NOT NECESSARY | 60.00 | - |

Report Ref No. CS3/INC21000255/Gtf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-----------|----------------------------|-------------------|
| | WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY). | | 36.00 | 30.00 |
| | | | 1,461.00 | 630.00 |
| | GRAND TOTAL | | 6,038.38 | 2,121.30 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 1,700.00 |
|--------------------------------------|------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | 30.31.55 F 13.00 | |

Report Ref No. CS3/INC21000255/Gtf3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part, Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.