Practicing Management Consultant (PMC) of SBACC Approved Training Organisation (ATO) of Workforce Singapore No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171

Our reference:

21-7205

Date:

15/1/2021

c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #03-46 Premier@KB Singapore 415875

Dear Sirs

RE:

Road Traffic Accident on 30/12/2020

Choon Hing Minimart

In accordance with your instructions received in this office or

5/1/2021

, we made arrangements to

examine the vehicle on

5/1/2021

at above-mentioned address. The following data was

recorded:

Vehicle details

Make	Mitsubishi	Registration	SLE1092J
Model	Attrage	Chassis	MMBSTA13AHH000411
Colour	Maroon	Gearbox	Auto
Odometer	243559km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

Tyre Depths

Front left	185/55R15	80% Yokohama
Front right	185/55R15	80% Yokohama
Rear left	185/55R15	75% Gremax
Rear right	185/55R15	75% Gremax

Status	REPAIRABLE		
Magnitude	Medium		
Legal status	Unroadworthy		

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$2,800.00 and 4 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd Infoknights International Services (Philippines) IABN Pte Ltd www.iaconsultingsg.com

Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference 21-7205

Date 15/1/2021

Page 2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
<u>List Items</u> :				
Front bumper	1	deformed/holder torn	856.50	856.50
Front bumper side retainer rh	1	damaged/nec	38.50	38.50
Front bumper fog lamp chrome ring rh	1	spilt	198.45	198.45
Front bumper chrome ring LED light rh	1	refix	265.50	0.00
Bonnet	1	repair.respray	896.50	0.00
Headlamp rh	1	defaced/holder cracked	798.00	798.00
Front fender rh	1	repair.respray	585.50	0.00
Front fender inner shield rh	1	torn	121.50	121.50
Front bumper lower grille	1	deformed/yield	199.40	199.40
Front radiator grille	1	inconsistent	452.80	0.00
	Sub- Total cost		4412.65	2212.35
^o ercent	age discount	: 10%	441.27	221.24
	Sub-Total cos	ts for parts	3971.39	1991.12
Special Nett Items:		-		
Front bumper clips	set	necessary	50.00	50.00
Front tyre rim rh	1	refinish	556.00	0.00
	Sub-Total cos	ts for parts	606.00	50.00
		=======================================		
Parts Repair				
*	*	*	0.00	0.00
	Sub- Tota	al costs	0.00	0.00
	Total costs	for parts	4577.39	2041.12
				

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**

Approved Training Organisation (ATO) of Workforce Singapore

Our reference

21-7205

Date

15/1/2021

Page

3

Section B: Labour Cost Calculation

To discountly usually have been determined to the second		ly rate	Manhr. Req.	Total	
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$	45.00	15	\$	675.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material	5	Sub-contract work.		\$	650.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$	40.00	
Specialist charges - Wheel alignment		-	-	\$	60.00
Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)	\$	45.00	0.8	\$	36.00
		Total la	bour cost	\$	1,461.00

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

Practicing Management Consultant (PMC) of SBACC

Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference

21-7205

Date

15/1/2021

Section C: Summary Table of Total Repair Cost

Description		Cost	
Damaged Parts Assessment (See section A)		\$2,041.12	
Labour Cost Calculation (See section B)		\$1,461.00	
Total cost		\$3,502.12	
Further discount	20%	\$700.42	
Total Repair Cost		\$2,800.00	

We would recommend a sum of	\$2,800.00	and	4	working days for repair.
No further items will be approved	without our expres	sed written agree	ement. Any sig	gnificant additional
items will be subject to a suppleme	entary report.			

Mechanical/Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma. Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

Enterprise Singapore - Recognised Certification for Management Consultants

IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)













































































