



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 3333D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	DENTED	1,685.00	899.00
1	BOOT LID INNER RUBBER	NOT NECESSARY	215.00	-
1	BOOT LID INNER LOCK	DAMAGED	285.00	145.00
1	BOOT LID WIPER ARM	NOT NECESSARY	120.00	-
1	BOOT LID WIPER MOTOR	NOT NECESSARY	480.00	-
1	BOOT LID KEY LOCK	NOT NECESSARY	185.00	-
1	BOOT LID HANDLE	NOT NECESSARY	165.00	-
1	REAR BUMPER	DEFORMED	1,325.00	625.00
2	TAIL LAMP @\$825.06	N/S CRACKED	1,650.12	285.00
1	REAR END PANEL-IN	TO REPAIR SEE LABOUR	350.00	-
1	REAR END PANEL-OUT	DENTED	480.00	480.00
2	REAR FENDER MUD SHIELD @\$88.10	N/S DEFORMED	176.20	88.10
1	REAR SPARE TYRE BRACKET	NOT NECESSARY	215.00	-
1	REAR NUMBER PLATE LAMP	NOT NECESSARY	38.00	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	951.00	-
1	REAR EXHAUST CHROME PIPE	NOT NECESSARY	185.00	-
1	REAR NUMBER PLATE	CRACKED	50.00	50.00
2	REAR BUMPER SIDE BRACKET @\$78.00	NECESSARY	156.00	64.00
	LESS 15% DISCOUNT		-	-395.42
			8,711.32	2,240.68
<u>SPECIAL NETT ITEMS</u>				
1	BOOT LID 70KM LOGO (SN)	NECESSARY	20.00	10.00
1	BOOT LID 5 PAX LOGO (SN)	NECESSARY	20.00	10.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	REAR CAMERA (SN)	DAMAGED	400.00	380.00
			790.00	600.00
<u>LABOUR</u>				
	REMOVE/REFIX REAR EXHAUST.		200.00	80.00
	TO REMOVE & REFIX REAR REVERSE SENSOR.		120.00	50.00

Report Ref No. CS/SMR21007523/Auf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL-IN AND REAR EXHAUST. SPRAY PAINTING CHARGES.		800.00	700.00
			800.00	700.00
			1,920.00	1,530.00
GRAND TOTAL			11,421.32	4,370.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,500.00

Report Ref No. CS/SMR21007523/Auf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.